

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 18 T 52N R 36W S _____ T _____ R _____ S 17 T 52N R 36W	5 (GCDB 140460) 7 (GCDB 300460)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10/30/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 18) North 1/16 corner, Sec. 18. Not previously monumented.

(7-Sec. 17) North 1/16 corner between Sections 16 and 17. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 18) Established the position for the corner midway and on a straight line between Quarter corner 1390.67' north and the Center of Section 18 1390.67' south.

(7-Sec. 17) Established the position for the corner midway and on the Section line between Section corner 1536.57' north and Quarter corner 1536.57' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Sugar N14°E 25.25' mrkd "1/16S BT"  
10" Sugar N63°E 2.95' do  
12" Sugar S33°W 19.9' do  
9" Sugar N49°W 17.45' do  
Set sq'd cedar post adjacent.  
E= 7853572.510 N= 237678.958

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Sugar N55°E 29.95' mrkd "1/16S BT"  
7" Sugar N76°E 19.75' do  
19" Sugar S58°E 6.25' do  
4" Sugar S57°W 15.2' do  
Set sq'd cedar post adjacent.  
E= 7855963.500 N= 237602.087

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL0502: N= 234995.272 m. E= 7857774.766 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

