

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 1 T 42N R 31W	5
	S T R	(GCDB 640660)
	S 1 T 42N R 31W	7
	S T R	(GCDB 700660)
	S T R	
3. Miscellaneous Property in Sec.		
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 7 04/28/14
5 04/24/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 1) Center-North 1/16 corner, Section 1. Not previously monumented.

(7-Sec. 1) North 1/16 corner between Section 1 T42N-R31W and Section 6 T42N-R30W.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 1) Established the position for the corner on a straight line between 1/4 corner 1253.77'
north and the Center of Section 1 1308.05' south, the position being proportionate to the dimensions
derived from the original U.S. plat of this township.

(7-Sec. 1) Established the position for the corner on the Range line between Township corner
1258.71' north and 1/4 corner 1317.33' south, the position being proportionate to the dimensions
given on the original U.S. plat of this township.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 5/8"x26" rebar with plastic cap "Mich DNR PS 33986" flush with the paved surface of Camp 5 Road. Set measuring nail with MDNR tag in: 11" R.Pine N37°W 54.05' mrkd "1/16S BT" 4" R.Pine N43°E 42.1' do 4" Maple S52°E 37.7' do 13" W.Pine S44°W 42.6' do E= 7912736.173 N= 143541.537	(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 10" Spruce S10°W 26.95' mrkd "1/16S BT" 4" Poplar N50°W 22.55' do 4" Poplar N55°E 5.75' do 5" Poplar S60°E 33.15' do Set sq'd cedar post adjacent. E= 7913539.754 N= 143530.221
---	---

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski Date 05/07/2014
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division