

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| Iron (County) | Located In: | Corner Code # |
|---------------------------------------|-----------------|--------------------|
| 1. Public Land Survey | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S 1 T 42N R 31W | 1 (GCDB 620700) |
| | S T R | |
| | S 2 T 42N R 31W | 4 (GCDB 520660) |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 1 | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

I, Stephan J. Szyszkoski, in a field survey on 4 04/21/14
1 04/30/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 1) West 1/16 corner common to Section 1 T42N-R31W and Section 36 T43N-R31W. Not previously
monumented.

(4-Sec. 2) Northwest 1/16 corner, Section 2. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 1) Established the position for the corner midway and on the Township Line between Section
corner 1334.76' west and 1/4 corner 1334.76' east.

(4-Sec. 2) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Tamarack N07°E 5.8' mrkd "1/16S BT"
7" Tamarack S40°E 7.2' do
8" Tamarack S23°W 3.2' do
7" B.Spruce N48°W 12.95' do
Set sq'd cedar post adjacent.
E= 7912336.520 N= 143935.615

(4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Poplar N21°W 12.75' mrkd "1/16S BT"
5" Poplar N48°E 14.4' do
5" Poplar S28°E 8.5' do
22" R.Pine S76°W 30.55' do
Set sq'd cedar post adjacent.
E= 7910720.598 N= 143579.451

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/07/2014

For the Michigan Department of Natural Resources, Forest Resources Division

