

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 35 T 42N R 32W	13
	S T R	(GCDB 560120)
	S 35 T 42N R 32W	16
	S T R	(GCDB 560100)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/26/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 35) Southeast 1/16 corner, Section 35. Not previously monumented.

(16-Sec. 35) East 1/16 corner **between** Section 35 T42N-R32W and Section 2 T41N-R32W. Not previously  
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 35) Established the position for the corner at the intersection of straight lines  
connecting opposite 1/16 corners.

(16-Sec. 35) Established the position for the corner on the Township line between Quarter corner  
1318.66' west and Section corner 1318.66' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
10" Oak N29°W 29.85' mrkd "1/16S BT"  
7" Spruce N67°E 35.35' do  
13" Maple S63°E 5.65' do  
12" Maple S48°W 33.05' do  
Set sq'd cedar post adjacent.  
E= 7901765.856 N= 134834.983

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" Spruce N26°E 31.05' mrkd "1/16S BT"  
11" Spruce S59°E 12.0' do  
11" Spruce S41°W 12.35' do  
13" Spruce N47°W 20.1' do  
Set sq'd cedar post adjacent.  
E= 7901758.798 N= 134430.263

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/01/2014

For the Michigan Department of Natural Resources, Forest Resources Division

