

MAR 9 2000

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey		T <u>42N</u> R <u>34W</u>	<u>J.K-3 (010)</u>
		T _____ R _____	_____
		T _____ R _____	_____
		T _____ R _____	_____
2. Property Controlling in Section	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____

IRON COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

99 DEC 30 AM 10:34

L.C. Records: 2.8, P. 137

*Gary L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

West Meander Corner to Sections 2 and 11, T42N, R34W

I, Gary L. Pisoni, in a field survey on March 23, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

## A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on October 10, 1851 by Guy H. Carleton, U.S. Deputy Surveyor  
Original Corner; Wood Post  
Original Bearing Trees:

Hemlock	10"	S 45° W	21 lks (13.86 feet)
Yellow Birch	12"	N 20° W	48 lks (31.68 feet)

PEER GROUP APPROVED

*Gary L. Pisoni*  
COUNTY REPRESENTATIVE

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored the corner position at record bearing and distance from a found Hemlock live bearing tree with scribing visible.

Meander Corner falls at edge of lake, set a W.C.M.C. on the West shore of Chicago Lake.

Corner record research on file with County Representative.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 1" diameter aluminum rod monument, 3 feet long and 3" above ground surface with a 2" diameter aluminum cap stamped as follows: Iron County Remonumentation, T42N, R34W, W.C., M.C., S-2, S-11, N 89° 35'E, 12.59', 1999, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Hemlock	16"	S 32° E	27.14 feet
Cedar	10"	S 33° W	25.05 feet
Yellow Birch	8"	N 87° W	22.25 feet
Iron Pipe	1"	S 67° W	1.45 feet
Steel sign post		S 55° E	0.75 feet



99-137

Signed by *Gary L. Pisoni* Date 12-28-99Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995