

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 31 T 44N R 32W	6
	S T R	(GCDB 160160)
	S 31 T 44N R 32W	5
	S T R	(GCDB 140160)
	S T R	
3. Miscellaneous Property in Sec.		
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 01/28/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 31) Northeast 1/16 corner, Section 31. Not previously monumented.

(5-Sec. 31) Center-North 1/16 corner, Section 31. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 31) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

(5-Sec. 31) Established the position for the corner midway and on a straight line between Quarter corner 1323.31' north and the intersection of 1/4 lines of Section 31 1323.31' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Blk. Ash S22°W 37.9' mrkd "1/16S BT"
4" Maple S37°W 23.3' do
5" Balsam S55°W 8.05' do
5" Maple N58°W 11.1' do
Set sq'd cedar post adjacent.
E= 7895617.099 N= 155076.824

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Maple N16°E 7.65' mrkd "1/16S BT"
5" Maple N81°E 23.3' do
5" Maple S69°E 24.6' do
5" Maple S29°E 8.95' do
Set sq'd cedar post adjacent.
E= 7895215.097 N= 155081.681

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski Date 03/09/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division