SURVEY & REMONUMENTATION

JAN 1 3 1998

JAN 1 3 1998					1. 1. /	97 DEC 2	3 PH 1	: 27
SECTION		ORNER REC				PEDISTRE	ds C:	7 P. 131
or corners in						Audio ita	or need	15
lron(County)	Located In:	: C(orner Code #		-		;	
. Public Land Survey	T <u>44N</u> R 32\ T R T R	w	D.E-7					
Property Controlling S S S S S	T R R T R R R R R R R R R R R R R R R R			_	: ' '	,	· ·	
Property in Sec. S	T R				Regi	ster of Deed	s Stamp &	File Numbe
. Lot No, Recorde . Private Claims							-	
ast Meander Corner between	Sections 17 and	1 20, T44N,	R32W	: :	1 A B	C D E	F G H	I J K L
Gary L. Pisoni	_, in a field survey	v on Novemb	ner 7 . 19.9	97	3 3	5	3	1-21
o hereby state that under requirementioned in lines 1 and 2 above vequired in the current manual of survivoreau of Land Management or by mentioned in lines 3, 4 and 5 above and Surveyors or by a Decree of ecovered, found as expressed below:	nents of P.A. 74, Movere in conformance by instructions of the a decree of a Courwere in conformance.	lichigan P.A. of with regulation United States I tof Law and / with the rules	f 1970, the comes and rules to Department of for that the comes of the Michigan	orner points therefore as the Interior, orner points an Board of	5	17	910	141
IOTE: Not more than 2 corners, all	in the same town ar	nd range, may b	e recorded		9			2
on this certificate.	:				10 30	29	28——27— 	26 2
. Description of original monun	nent and accessori	es and/or subs	sequent resto	ration:	11 12 31	32	 3334	35 -3
Original corner established by Original Corner: Wood post Original Bearing Trees:	,		Surveyor, in .	July 1849.	13	PEER G	OUP AP	PROVED
	Hemlock 10" W. Pine 18"	\$58°E N76°E	23 links(15. 17 links (11		T.	How L. F.	REPRES	PROVED 1/-//-917 ENTATIVE
B. Description of corner evidence	ce found and/or me	ethod applied i	in restoring o	r reestablish		•		
No evidence of original B.T.s f	· found					,		:
Found a 3/4" iron pipe located Plat of Gov't Lot No. 1 - Secti		of Light Lake	as the mean	der corner a	s shown o	n the Houlm	ont Unrec	orded
Accepted iron pipe as the best Corner on higher ground.	t available evidenc	e for restoring	corner positi	ion. I set a	W.C. M.C	. 8.0 feet Ea	st from M	leander
Corner record research on file	with County Repre	esentative.		,	:	·	•	
C. Description of monument f	for corner and acce	essories establ	lished to perp	etuate loca	ing the po	sition of the	corner:	
At the W.C. M.C. position, se ground surface and stamped a 1997, RLS-27457 from which No scribing or signs on B.T.s.	as follows: Iron Co n I established the	unty Remonur following bear	mentation, T4	14N, R32W, Il measurem	8.0' Wes ents taken	t, W.C., M.	.C., S-17, side of tre	S-20 e)
Red Mapl White Pir White Pir	ne 2	8" S 5 20" S 3	7°E 7°E 1°E	15.87 feet 32.68 feet 38.47 feet	:		Artendrate	OF MICHIGA
Red Pine M.C.	The second secon	-	7°W est	10.72 feet 8.0 feet	. !			BARY L. 🤼 PISONI
97-26	2			. [1000	4	LAND URVEYOR
Signed by Aug 7. 12	07457		Date	<u> </u>	<u>November</u>	0, 1997	6/0	No. 27457
Surveyor's Michigan License No.	27457	<u></u>	FORM APPROVED	BY MICHIGAN ST	ATE BOARD OF	PROFESSIONAL SU	RVEYORS JAN	Del give lack
			· · · · · · · · · · · · · · · · · · ·				11111	REVISED MAY 14 HEVISED JAN REVISED OCT

IRDIT COUNTY
HIGHIGAN
RECEIVED FOR RECORD