

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM12: 59

L.C. Record: 11-8-P-234

*Gary L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

for corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 34W	A-3 ✓
	T 44N R 35W	M-3
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Section Corner to Sections 1 and 12, T44N, R35W  
Section Corner to Sections 6 and 7, T44N, R34W

I, Gary L. Pisoni, in a field survey on March 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by William A. Burt, U.S. Deputy Surveyor.

Original Corner; Spruce Post

Original Bearing Trees:

Hemlock	10"	N 30° E	25 links (16.50 feet)
Hemlock	18"	S 16° W	30 links (19.80 feet)

In August, 1851, Guy H. Carleton, U.S. Deputy Surveyor established the following new bearing trees:

Hemlock	24"	N 39° W	16 links (10.56 feet)
Sugar	10"	S 40° E	34 links (22.44 feet)

On 10/1/75, Arthur O. Enger RLS DNR restored the section corner position from the remains of a Hemlock bearing tree, being 18" in diameter, S16 W, 30 links and set a 1" diameter by 36" iron pipe with a 3 1/2" diameter aluminum cap stamped as follows: T44N, R35W, R34W, S-1, S-6, S-12, S-7, 10/1/75, RLS 13581. Recorded in Liber 1, Page 511 of LC records.

1975 Bearing Trees:			
Sugar Maple	7"	S 45° W	26.3 feet
Sugar Maple	7"	S 82° E	7.5 feet

PEER GROUP APPROVED  
*Iron Range Survey 11-30-2000*  
COUNTY REPRESENTATIVE

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found remains of Hemlock B.T. On 3/18/2000 found monument as describe above and the following bearing trees:

Sugar Maple	12"	S 76° E	7.71 feet
Sugar Maple	8"	S 48° W	26.52 feet

Found existing bearing trees and steel rail which were established by the U.S.F.S. as described below:

Sugar Maple	11"	N 57° W	36.34 feet
Sugar Maple	8"	N 31° E	18.77 feet
Steel sign post		N 75° E	2.55 feet

Monument is 6" above ground surface.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

00-002  
Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995

LIBER 8 PAGE 234

