

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 5 T 45N R 34W S _____ T _____ R _____ S 4 T 45N R 34W	12 (GCDB 240620) 1
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 320700) _____ _____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 12 08/24/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 5) Center-South 1/16 corner, Section 5. Not previously monumented.

(1-Sec. 4) West 1/16 corner between Section 4 T45N-R34W and Section 33 T46N-R34W. Not previously
monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 5) Established the position for the corner midway and on a straight line between Quarter
corner 1307.33' south and the Center of Section 5 1307.33' north.

(1-Sec. 4) Established the position for the corner midway and on the Township line between Section
corner 1321.75' west and Quarter corner 1321.75' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Sugar N17°E 13.6' mrkd "1/16S BT"
8" Sugar S22°E 16.6' do
12" Sugar S32°W 11.2' do
10" Sugar N46°W 18.7' do
Set sq'd spruce post adjacent.
E= 7877910.563 N= 172290.091

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N75°E 14.15' mrkd "1/16S BT"
4" Sugar S18°W 14.3' do
4" Sugar N83°W 15.3' do
4" Sugar N20°W 24.75' do
Set sq'd cedar post adjacent.
E= 7879133.707 N= 173468.882

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski Date 09/15/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division