

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 4 T 45N R 34W S _____ T _____ R _____ S 4 T 45N R 34W	12 (GCDB 340620) 8
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 320640) _____ _____
4. Lot No. _____, Recorded Plat	_____	_____
5. Private Claims	_____	_____

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 08/25/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 4) Center-South 1/16 corner, Section 4. Not previously monumented.

(8-Sec. 4) Center-West 1/16 corner, Section 4. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 4) Established the position for the corner midway and on a straight line between 1/4 corner
1312.26' south and the Center of Section 4 1312.26' north.

(8-Sec. 4) Established the position for the corner at the intersection of the E-W 1/4 line with the
West 1/16 line. The E-W 1/4 line is parallel to the weighted mean bearing of the two lines G3-F3
and F3-E3. The West 1/16 line originates at 1/16 corner #1 and runs S00° 58'01"W (MCS83 grid
bearing), being parallel to the weighted mean bearing of the N1/2 of the N-S 1/4 line and that part
of the West line of Section 4 which is north of Porter Lake.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Sugar N11°E 15.25' mrkd "1/16S BT"
8" Sugar S56°E 12.7' do
15" Hemlock S03°E 25.95' do
8" Sugar N51°W 4.2' do
Set sq'd cedar post adjacent.
E= 7879515.269 N= 172259.831

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Sugar S86°E 7.5' mrkd "1/16S BT"
6" Sugar S11°W 3.45' do
10" Sugar S72°W 12.05' do
9" Sugar N07°W 6.2' do
Set sq'd cedar post adjacent.
E= 7879120.260 N= 172672.155

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/15/2015

For the Michigan Department of Natural Resources, Forest Resources Division