## LAND CORNER RECORDATION CERTIFICATE

For corners in	i ming requirement of Ac	1. 74, Mich. P.A. 1970 as Ame	ended
, av <b>2011,0,0 11,</b>			1
Iron	Located In:	Corner Code #	•
(County)			
1. Public Land Survey	T R		
·	TR		
2 Property Controlling	T R		
		4	
	S 22 T 46N R 34W	(GCDB 420360)	
3. Miscellaneous	STR	(GCDB 460360)	
Property in Sec.	S_T_R_		
4. Lot No. Red	corded Plat		Register of Deeds Stamp & File Number
5. Private Claims		<del></del>	ABCDEFGHIJKL
	4 12	2/15/14	2 - 6 - 5 - 4 - 3 - 2 - 1
i, Stephan J. Szyszkoski , ir		10045	3
			4 7 9 9 10 11 11
above were in conformance with	regulations and rules therefore as require	red in the current manual of survey	,5├ <del>─┼─┼─┼─┼─┼─┼</del>
instructions of the United States	Department of the Interior, Bureau of I	and Management or by a decree of	6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Comed Survey  T R  2. Property Controlling S 22 T 40N R 34W     3. Miscellaneous S T R  COCD8 460350  Property in Sec. S T R  COCD8 460350  Proper			
re-established, monumented, recov	ered, found as expressed below:	or a Court of Law; established,	8 -19 -20 -21 -22 -23 -24
	•		
NOTE: Not more than 2 corn	ners, all in the same town and range	e, may be recorded	
	_		
			12 -31 -32 -33 -35 -36
A. Description of original m	onument and accessories and/or	subsequent restoration:	
(4 000 00) 11	.0	7.5	LE OF MICH
(4-bec. 22) Northwest	. 1/16 corner, Section 22.	. Not previously monume	ented.
	£		LAND
			- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
(6-Sec. 22) Northeast	1/16 corner, Section 22	. Not previously monum	33986 33986
		Pool	CANDSURVE
		81	Manager 1
B. Description of corner evi	idence found and/or method app	lied in restoring or reestablish	ing corner:
		3	
(4-Sec. 22) Establish	ed the position for the (	corner at the intersect	ion of straight lines connecting
opposite 1/16 corners	•		The starting
		59	
(6-Sec 22) Establish	ed the position for the		
opposite 1/16 corners		corner at the intersect	cion of straight lines connecting
C. Description of monument	t for corner and accessories estal	blished to perpetuate locating	the position of the corner:
743 G 3 4899 GG 2 2			
(4) Set 1"IDx28" I.pi	pe with 2" alum. MDNR car		3" I.pipe with 2" alum. MDNR cap.
12" Cedar N34°W 17.25			hail with MDNR tag in the side of
12" Cedar S77°E 6.35'		F	200 25 65
		4" Tamarack S01	l°W 14.8'
			0°W 3.8' do
		Set sq'd cedar E= 7881634.020	post adjacent. N= 177860 555
	22		
Bearings are magr	netic. Coordinates are MCS	383 in meters, NAD83(20	11) Epoch 2010.00 datum.
Coord.	kei.=NGS PID RL0476: N=	196482.411 m. E= 78792	34.516 m.
Signed by	15/2 /2/	D-4-	05/40/0045
- Vingora	- July	Date	05/19/2015
Surveyor's Michigan License No.			
For the	e Michigan Department of Natural Re	sources, Forest Resources Division	n