

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

MAR 01 2000

SECTION

For corners in

KALKASKA

(County)

Located In:

Corner Code #

1999 REMONUMENTATION

1. Public Land Survey

T 25N R 7W

E-8

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property In Sec.

S

T R

S

T R



3020159

Page: 1 of 1
02/04/2000 03:40P
REMON
LB: 6 PG: 105

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, EUGENE FARRIER, in a field survey on November 9, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-8: 1/4 Cor. Common to Sec. 20 & 21, T25N-R7W, Garfield Township

1853, G.L.O. Resurvey, by V.W. Caukin (Deputy Surveyor), Co. Survey Notes Pg 60, set 1/4 Section post, Beech 14", S38°E, 25 Lks; Beech 12", S83°W, 10 Lks

1912, Fargo Survey, no U.S. evidence found, Maple 20" West, 2.84 1/2 Ch; Hemlock 16", S5.5°W, 3.17 1/2 Ch

1973, Survey & LCRC, by J.F. Erickson, (Survey recorded in Liber 1, Pg. 285; LCRC recorded in Liber 1, Pg. 193) found 3/4" square rod in mon box 0.5' West of centerline of M-66, S50°W, 24" Poplar, 118.35'; N55°E, 12" Poplar, 78.20'; Due East, top center 9" square r/w mon., 74.85'

1978, Survey, by N. Parker, (recorded in Liber 2, Pg. 282), same as Erickson (1973)

1980; 1983; 1987; 1988, Survey, by E. Farrier (Co. Surveyor), found 1/2" iron in mon box, witnessed in Liber 2, Pg. 26

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-8: 1/4 Cor. Common to Sec. 20 & 21, T25N-R7W, Garfield Township

Found boat spike in mon. box 0.5' West of centerline of M-66.

East, 75.00', iron & cap #24594

S62°E, 71.20', 4" Poplar, set nail & washer

S70°W, 69.26', 12" Poplar, set nail & washer

N68°W, 76.26', 5" Poplar, set nail & washer

No G.L.O. witnesses were found.

Ratified by Peer Group

P.A. 345 - 1990 Kalkaska County

Chairman

Date

Eugene Farrier

02-03-00



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-8: 1/4 Cor. Common to Sec. 20 & 21, T25N-R7W, Garfield Township

Found boat spike in mon. box 0.5' West of centerline of M-66. Added aluminum cap.

East, 75.00', iron & cap #24594

S62°E, 71.20', 4" Poplar, set nail & washer

S70°W, 69.26', 12" Poplar, set nail & washer

N68°W, 76.26', 5" Poplar, set nail & washer

Kalkaska County Peer Group accepted the above monument as the best available evidence of the position of the original corner.

Signed by

Michigan License No. 24594

Date

02-04-00

Surveyor's