## SURVEY &

MAR 1 9 1997

## LAND CORNER RECORDATION CERTIFICATE

For	corners in COMMIS	SSION	Filing Require	ment of Act 74, Mi	ich. P.A. 1970	REGISTER'S OFFICE	
10	Keweenaw		ed In:	Corner Code ≠		County of Kewsenson 1 SS	0姓.
	(County)	COCAI	.eu iii.	Conner Code ===		day of December 1	
1	Public Land Survey	т	58 R 29	1 - 3/4 (8	) -		10 00
١,	rabile Land Garvey	· †_	58 R 29	H - 2		in Liber of L on page 157	
			R :		_	toberdo Bosenheuses	
_			<u>R</u>		-	Register	of Deeds
2.	Property Controlling in Section		R				or incees
3	Miscellaneous		R		Pos	ister of Deeds Stamp & File Nu	mbar
•	Property in Sec.	S T _	R		_ neg	ister of Deeds Staffip & File Hu	
4.	Lot No.	Recorded Plat _				ABCDEFGHI	J K t :
	Private Claims				· · · · · · · · · · · · · · · · · · ·		
		·				2 - 5 5 6	Ż - -
						3	<del> - - -</del>
	John I. Haataja	: 4:-1-4	Sont	emben 20	. 06	*	111212
	porm 1. macaja nereby certify that under re					5	<del>   -</del>
19 <b>li</b>	nes 1 and 2 above were i	in conformance wi	th regulations and	rules therefore as requ	uired in the	6 - 18 - 17 - 18 - 15 - 15	1'4
	ent manual of survey instr					7 <del> - - - - - - - -</del>	╂┼┼
	agement or by a decree of ve were in conformance wi					8 -19 -20 -21 -222	324-
Cou	rt of Law; established,	re-established, m	onumented, re-mo	numented, recovered,	, found as	° <del>}</del>	<del>├─┤</del> ─
	essed below:				-	10 30 29 28 27 2	e25
МОТ	TE: Not more than 4 c		e same town and	range, may be reco	rded	<sup>11</sup> } <del></del>	<del>├─</del> ├─
	on this certificate.	•	:		·	12 31 32 34 34	536
A.	Description of original	monument and a	accessories and/	or subsequent restor	ration:	13	<u> </u>
	I-3/4 Meander o	cor. orig. c	all 31.40 Ci	i H-2	Cent. of	Sec 3	
		. cor. 10	1			orig. survey	
	Wood Post	;	!			o or right burney	
	Cedar 12"	N 40 E 12	lks.				
	Cedar 6"	' N 20 W 18	lks.			•	
			:				
		•					
Ξ.	Description of corner e	vidence found ar	nd/or method ap	plied in restoring or r	reestablishing o	corner:	
	I-3/4 No eviden	ce of orig.	cor. FND.	H-2	Tree marke	ed approx. cor.	
	Set M.C.	on sec. line	- 1	4.5.5.4.	Establishe	ed at intersection of	
			0 350	F M/C/h	N-S & E-W	1/4 lines	
			N. P. John			1.9	
	•			HN I. ATAJA	_	a I	
				AND		tified by Peer Group	
			子子 sur	RVEYOR =	· in acc	cordance with P.A. 345	
			200	NO. /2 -	Co. Rep	Imis Mitellit.	
	•			9833	Date	12/6/95	
			CO T	AND S	<i>5010</i>	the state of the s	
n	escription of monument		16117	33344			
ľ	escription of monumen			iblished to perpetuat	e locating the p	position of the corner:	
1	-3/4 M.C. on Ea	st line Sec	. 10	H-2	Cent. of Se	ec. 3	
	14" Y Riv	e with brass ch N 60 W ]:	s cap		Set 1" pipe	with brass cap	
	8" Maple	N 23 E 18	8 95'		5" Uak	N 49 W 5.03'	
	3" Cedar	S 8 E 16	6.74' :		6" Oak	N 75 E 9.30'	
	4" Cedar	S 85 W 26			o" w. Bircr 5" Oak West	5 38 E 16.051	
					- CUN MESI	, 64.00	
				•		•	

or's Michigan License No.