

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

For corners in

Macomb
(County)

Located In: Washington Township

Corner Code #

OCT 19 1998

SECTION

1. Public Land Survey

T 4N R 12E A-7

T R

T R

T R

2. Property Controlling
In Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD
ON 10/20/98

WILLIAM E. SODERBERG, P.S., CHAIRMAN

4. Lot No. Recorded Plat

5. Private Claims

I, Huston K. Kennedy, in a field survey on February 14, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1817-GLO Wampler, D.S.; Set Post 14" Black Oak N27°W 188 Links
 - 1974-Avey, PS #15396; LCRC L.2496, Pg.760 - Fnd 1/2" Bar
 - 1983-Buckerfield, PS #10888; LCRC L.3546, Pg.450 - Fnd 1/2" Bar
 - 1982-Avey, PS #30076; LCRC L.5290, Pg.296 - Fnd a 1/2" Bar
 - 1974-Avey, PS #15396; Survey L.2496, Pg.747 - Fnd Iron Bar, no witnesses
 - 1991-Avey, PS #30076; Unrecorded Survey - Fnd 1/2" Bar, used same wit as 1982 LCRC

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 4" diameter Concrete Monument w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445 at the base of an old wooden fence post 1 foot above the surface, with a fence extending to the South and West. The corner is being accepted and used as a common corner with Sections 13 & 24, T4N, R11E, Oakland Township (M-7).

Witnesses from LCRC #1, 2 & 3 were used to recover and verify the location of the found 4" diameter Concrete Monument w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445.

I accepted the found 4" diameter Concrete Monument w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445 as the best evidence of the original corner position.

FIELD MEASUREMENTS BETWEEN

A-7 to A-6

No GLO, 2655.65 FL (GPS-GROUND)

Unrecorded Survey by Warren C. Avey, PS #30076 = 2655.82 Ft.

A-7 to B-7 (B-7 has not yet been review or approved by peer group)

GLO = 40.60 chains or 2679.60 FL & 2700.43 FL (GPS-GROUND)

Unrecorded Survey by Warren C. Avey, PS #30076 = 2674.46 Ft.

A-7 to A-8

No GLO

Survey recorded in Liber 2496, page 747 = 2650.35 Ft.

2650.41 FL (GPS-GROUND)

A-7 to M-7

GLO, Common Corner

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- A-7 I accepted the found 4" diameter Concrete Monument w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445
- Due North 5.99' Fnd PK Nail & Remon Washer #22445 West face 9" Oak
- Due East 15.41' Fnd PK Nail & Remon Washer #22445 South face 5" Oak
- S02°W 8.98' Fnd PK Nail & Remon Washer #22445 East face 4" Oak
- N45°E 15.00' Fnd PK Nail & Remon Washer #22445 SE face 5" Oak

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by: [Signature]

Date 7-2-98

Surveyor's Michigan License No. 7623

