APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

11/95/28/7

LAND CORNER RECORDATION CERTIFICATE

	<u> </u>	 \sim	4	
	<u></u>	 -		7/
For	corners in			~

Filing Requirement of Act 74, Mich. P.A. 1970

216

	MIDLAND (County)	Located In:	Corner Code ##	STATE OF MICHIGAN MIDLAND COUNTY
1.	Public Land Survey	T13N R2W	E-9	FILED
		. T R T R		19 JUL 95 10:52 A.M.
2.	Property Controlling	T R S T R		BEVERLY J THAYER
۷,	in Section	S T R		REGISTER OF DEEDS
3.		S T R S T R		Register of Deeds Stamp & File Number
	rroperty in Occ.	· · · · · · · · · · · · · · · · · · ·		
4.	Lot No	, Recorded Plat		
5.				A B C D E F G H I J K L
				2 6 5 4 3 2 2
				3
	•	•		4

PAUL B. LAPHAM , in a field survey on MAY do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration: E-9 Corner common to Sections 21, 20, 29 & 28

1852 AUSTIN BURT, SET POST, HEMLOCK 13" N33W 45 LKS., HEMLOCK 14" S64°E 34 LKS.

1899 COUNTY SURVEY RECORDS, WEST LINE SECTION 21 IS 80.14 CH. MEAS. 5290.60 (80.16)

3-05-73 A.V. COURTRIGHT, 5/8" ROD IN MON. BOX (132) 1-384

4-12-73 A.V. COURTRIGHT, L.C.R.C. #239

4-91 GRAY, FOUND MON. BOX, L.C.R.C. #704

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dosier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-9 Corner common to Sections 21, 20, 29 & 28

Found 5/8"x18" re-bar & 1"x1/4" flat iron in Mon. Box. Replaced with 5/8"x18" re-bar. Replaced Mon. Box. CSR notes West Section line is 80.14 ch. meas. 5290.60 (80.16) North. Found witnesses per surveys by Courtright and Gray.

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, E-9 was approved for remonumentation at a Peer Review Committee Meeting on 6-6 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9 Corner common to Sections 21, 21, 29 & 28
Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box per Surveys by Courtright and Gray. Accepted as best available evidence of the accepted position of the corner.

N47W 52.08' - POWER POLE N23'W 103.48' - POWER POLE N48'E 53.09' - TELE, STUB N79'E 202.52' - POWER POLE

MATE OF THE OF MICHIGAN PAUL B. LAPHAM PROFESSIONAL SURVEYOR Decree of the second

kne 7, 1995

Surveyor's Michigan License No. ___