## SURVEY & REMONUMENTATION

MAR 1 3 1998

Surveyor's Michigan License No.\_

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

•	 						
		LANI	CORNER	RECORD	ATION	CERTIF	FICA

SECTION Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

1997 DEC 26 PH 12: 44

MARQUETTE (County)	Located In:	Corner Code #	Part.	Sicin A. Monlay GISTER OF DEEDS Of
Property Controlling	T <u>45N</u> R <u>24W</u> TR TR TR S T R	C-5		
Property Controlling     in Section	S TR			
Miscellaneous     Property in Sec.	S T R S T R		LIBER Register of	PAGE 12 Deeds Stamp & File Number
	corded Plat			
o. Filvate Claints	······································		1 A B C	DEFGHIJK LM
· ;			2 - 6	5 - 4 - 3 - 2 1
do hereby state that under re mentioned in lines 1 and 2 a required in the current manual of Bureau of Land Management	, in a field survey on, equirements of P.A. 74, Michigan above were in conformance with roof survey instructions of the United or by a decree of a Court of La	P.A. of 1970, the corner egulations and rules theref States Department of the Ir w and/or that the corner	points 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	8 9 10 11 12   17 16 15 14 13
mentioned in lines 3, 4 and 5	above were in conformance with three of a Court of Law; established	ne rules of the Michigan Bo	ard of 7	20 21 22 23 24
recovered, found as expressed		ed, re-established, mondin	9	20
NOTE: Not more than 2 c on this certificate.	orners, all in the same town and	I range, may be recorded		29. 26. 27. 26. 25
C-5: Section Corner commo 1852: A. Sullivan's original wood post referenced by:	nonument and accessories and/on to Sections 7, 8, 17, and 18, subdivision survey notes describe	be the corner monument	as a	D BY PEER GROUP
6" Spruce Pine N78W,		Pine S32E, 12 L	La	of 1990 my A Busane
	rernment Corner Index Book (F.B I Jack Pine post referenced by: 31.2' 4" J. Pine		DATE_	1/12/15/97
No Date: The M.C.R.C. Gov	ernment Corner Index Book (F.B	3. #642 - Sec. 18) indica	tes the corner as a 1"	Iron Pipe and Jack Pine post
4" Dry J. Pine S38E,	15.6' 4" Dry J.	Pine S37W, 10.4'		
1944: Survey field notes from the been killed by a forest fire substitution of the sub	om M.C.R.C. F.B. #712 (No pg. o blazes were not scribed, and t 31.2' 4" J. Pine	rees were witnessed by	er as a set Pipe and Ja placing tacks on blaze	ck Pine Post. Trees had all es of:
C-5: 1997: No original corneground, and stamped to ide	vidence found and/or method ap er evidence found. Found and ac ntify the corner. Found existing 2634.82' and distance West is	ccepted a 1 1/4" O.D. Pi references as noted in P	pe with a 4" diameter	Aluminum Cap, 0.6' above tre no nearby line calls available
C-5: 1997: Stamped "MCR	nt for corner and accessories es 1997" on found aluminum cap 22.68' (to set d.h. nail) (Babbitt S14W, 27.28' (Babbitt	ped monument. Measure NBT) P. Pole	d found references: S58E, 18.96' (to	f the corner: fd. nail/washer) (BabbittNBT) set d.h. nail)
4" Squared Wood Post Established new references:		FU L Disc.	NOIE EE OOL	
Orange Steel Sign Post w/	inted face, butt, and side nail bl	5" J. Pine S88W, 0.9' azes, d.h. measuring nai	N61E, 55.23'	TE OF SICING
				GERALD W. *  CARLSON *  SURVEYOR *

## C-5: PART A CONTINUED:

No Date: The corner is shown on a map of Sharkey's Unrecorded Plat. No description of corner object or accessories given.

1973: The corner is shown on a Survey Map recorded by D.T. Bogren, P.E. in L. 300, Deeds Pg. 39. No description of corner object or accessories give Distance N89-55'W, 2440.54' to a set meander corner (Iron Pin) on the East side of Provost Lake.

1976: A Survey Map by David B. Babbitt P.S. #21558 for the M.D.N.R. indicates the comer as a standard D.N.R. Monument. Distance N00-29'-24"W, 2634.9' to the West 1/4 Corner of Section 8. Distance S89-24'-05"E, 2628.70' to the South 1/4 Corner of Section 8. Distance S00-13'-00W, 2702.44' to the West 1/4 Corner of Section 17. No accessories given.

1976: An LCRC recorded by David B. Babbitt P.S. #21558 in L. 1, RC Pg. 163 indicates the corner as a found 3/4" Pipe recorded at the Marquette County Road Commission Office, and offers the following explanation for the perpetuation of the found corner position, "The South 1/2 mile of the We Line of Section 5 as monumented measures 2551.9' - the distance North from the Corner of Sections 5, 6, 7, and 8 to a pond was originally recorded a 231' - it now measures 150' +/-. The West line of Section 17 as monumented measures 5404', Fer these reasons I believe that the original position of these three corners was 100' plus or minus South of their present position. However, they are corners of long standing and have been used in numerous previous surveys. Therefore; as expressed in an opinion by Justice Thomas M. Cooley of the Michigan Supreme Court, in 1881, I believe that it would demischief to attempt to move them at this time." Babbitt replaced the found 3/4" Pipe with a 1" Pipe with 4" Aluminum Cap and Cedar Post. Reference by nails and roofing caps in the side of:

7" J. Pine

N79E.

8" J. Pine

SORW

ידכ דכ

Power Pole

S58E, 18.98'

32.70

1977: A Certificate of Survey recorded by Mel Davis P.S. #16926 in L. 329, Deeds Pg. 756 indicates the corner. No description of corner object or accessories given. Distance N00-29'-25"W, 2634.82' to a found D.N.R. Monument at the West 1/4 Corner of Section 8.

1979: A Certificate of Survey recorded by Charles F. Clark P.S. #25836 in L. 333, Deeds Pg. 821 indicates the corner as a Pipe and D.N.R. Cap. Distance NOO-29'-25"W, 2634.82' (R) to a D.N.R. Monument at the West 1/4 Corner of Section 8.