SURVEY & REMONUMENTATION

MAD 1 2 1000

MARQUETTE COUNTY

BILLI T 0 1220				RECEIVED FOR RECORD						
SECTION		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970			1997 DEC 26 PM 12: 45					
For corners in MARQUETTE (County)	Located In:	Corner Code #	Property Control	Path	idais A	P. M.	mls. DS 0	gh.		
1. Public Land Survey	T <u>45N</u> R <u>25W</u> TR TR	<u>K-5</u>						**		
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	T R R T R R T R R T R R T R R T R R T R R T R R T R R T R		LIBER	2 PA	GE 25		Mussah			
4. Lot No, Records 5. Private Claims	ed Plat		1 A	B C D	E F G	н	I Ј	K L		
do hereby state that under requiremmentioned in lines 1 and 2 above virequired in the current manual of survibureau of Land Management or by	nents of P.A. 74, Michigan were in conformance with ey instructions of the United a decree of a Court of Li	regulations and rules therefore a I States Department of the Intério aw and/or that the corner poin	as 5 — or, 6 — 1	7 8	9-16-	10 15	11	12		
mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree of recovered, found as expressed below:	a Court of Law; establish		•• _f	9 20-	21	-22	23	24		
NOTE: Not more than 2 corners on this certificate.	, all in the same town an	d range, may be recorded	10 3	8029	28	27 	26-	25		
A. Description of original monum K-5: Section Corner common to S			123	132	3'3	—34— 	35	36		

No Date: The M.C.R.C. Government Corner Index Book (F.B. #643- Sec's. 12, 13, and 14) indicates the corner as an Iron Rail. No accessories given.

14" Spruce Pine N70E,

(SEE REVERSE SIDE)

a Spruce Pine post referenced by:

Spruce Pine S26W,

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1852:Martin M. Hall's original subdivision survey notes describe the corner monument as

No Date: Survey field notes from M.C.R.C. F.B. #573, pg. 25, indicate the corner as an

K-5: 1997: No original or subsequent corner evidence found. Found three existing references as noted on LCRC by Glenn Van Neste, P.S. #27464, in L. 4, RC Pg. 36. Re-established corner using recorded distances from three found references. Corner is in small opening in jack pine stand, +/- 200' East of the N.E. end of a small lake. Checked Line Call: West, 9.55 chains (630.30'), 24" Y. Pine. Measured Line Call: Measured West 630' and found no evidence of 24" Yellow Pine (Entire area was burned over in 1986 according to Bruce Spike, a local forester). Checked Line Call: South, descend hill from post S.E.; 5.00 chains (330'), foot and ascend hill 30' S.E.. Measured Line Call: Measured South 330' and hit foot of hill to North and began ascent of hill to South coursing S.E. - call fits very well. Distance East is 2631.16', distance West is 2582.45' and distance North is 2630.15'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-5: 1997: Re-established corner using a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is +/- 1' above ground. Measured distances from d.h. nails set directly below found nails in found references:

8" J. Pine 8" J. Pine

N53W, S50E.

36 L

Iron Bed Rail on Jack Pine Plains. No accessories given.

53.21' (Set d.h. nail below chisled out nail, S. side, 3' high) (Van Neste NBT)

65.72' (Set d.h. nail below chisled out nail, S. side, 2' high) (Van Neste NBT)

54.04' (Set d.h. nail below fd. nail & washer #17618, W. side, 5' high) (Van Neste NBT)

RATIFIED BY PEER GROUP

345 OF 1990

13" J. Pine N01W, Established new reference:

5" J. Pine

S22W.

44.85' (Set d.h. nail W. side, 1' high)

Green Steel Sign Post w/ Yellow Survey Marker Sign

N39W, 3.0'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

OF MIC GERALD W CARLSON SURVEYOR No. 24589

GenellaCalk

K-5: PART A CONTINUED:

1942: Survey field notes from M.C.R.C. F.B. #712 (no pg. given) indicate they set up on a hub (set by someone for the corner), and went S88-55'E, 26.5' and set a 1" Iron Pipe and Jack Pine Post for the corner. No bearing trees were available.

No Date: The M.C.R.C. Government Corner Index Book (F.B. # 643 - Sec. 11) indicates the corner as a 1" Iron Pipe and J. Pine Post. No available bearing trees.

No Date: The corner is indicated on an unidentified sketch of Co. Rd. 553. No description of corner object or accessories given.

1980: An LCRC recorded by Glenn C. Van Neste P.S. #27464 in L. 4, RC Pg. 36 indicates the corner as a found 3/4" Pipe bent over. Van Neste straightened and reset the pipe. Referenced by:

4" J. Pine

N57W,

53.21

10" J. Pine

N03W.

54 041

3" J. Pine

S53E,

65.72

1985: The corner is indicated on a map of the Proposed K.I. Sawyer Pipeline by Michigan Consolidated Gas Company (Drawing # MC-8976-1). No description of corner object or accessories given.

1989: The corner is indicated as a found 1" Iron Pipe on a Utility Easement Location Sketch recorded in L. 001, SM Pg. 634. Distance, S00-09'-32"E, 2618.72' to a found 1" Iron Pipe at the West 1/4 Corner of Section 13. Distance, N89-22'-57"E, 2630.10' to a found 5/8" Rerod with R.L.S. Cap #27464 at the North 1/4 Corner of Section 13. No accessories given.