

DEC 01 1993

OTTAWA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 NOV 11 AM 11:56

For corner in COMMISSION

REGISTER OF DEEDS  
OTTAWA COUNTY, MI

Ottawa (County) Located In: Corner Code ##

1. Public Land Survey	T <u>5N</u> R <u>15W</u>	<u>E-13 (SW Sec 33)</u>
	T _____ R _____	<u>Holland Twp.</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, David R. Greer, in a field survey on September 13, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Recorded in Liber 3, Page 5, Dec. 11, 1975

E-13

PK Nail in Power Pole	S-SE	34.82'
Nail & Tag on 24" Maple	N-NE	71.35'
PK Nail in Power Pole	NW	68.40'
Railroad Spike	W	21.22'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-13

Found Railroad Spike over 2" square iron in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner

PK Nail in Power Pole	S-SE	34.82'
Nail & Tag on 24" Maple	N-NE	71.35'
PK Nail in Power Pole	NW	68.40'
Railroad Spike	W	21.22'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13

Set Ottawa County Remonumentation Iron &amp; Cap over 2" square iron in monument box

AZ - Michigan State Grid Direction

NW Cor Brick Building	AZ. 155°48' 00" 111.40'
SW Cor Brick Building	AZ. 158°49' 18" 126.22'
SW Cor Brick Building	AZ. 46°43' 00" 95.79'
SE Cor Brick Pillar	AZ. 49°05' 37" 100.14'
CL Hydrant	AZ. 348°56' 00" 125.25'
NW Cor Brick Building	AZ. 29°12' 00" 153.30'
NE Cor Brick Building	AZ. 254°18' 00" 176.49'
Remon. iron in monument box (E-1 T4N R15W)	AZ. 270°43' 21" 21.25'

Signed by David R. Greer  
Surveyor's Michigan License No. 16042

Date Sept. 13, 1993