

Ottawa County Remonumentation

RECORDED

LAND CORNER RECORDATION CERTIFICATE

93 DEC 15 AM 9:29

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

Ottawa

(County)

Located In:

Corner Code ##

Robinson Township

1. Public Land Survey T 7N R 15W I-12
T _____ R _____ W 1/4 corner
T _____ R _____ Section 35
T _____ R _____ _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Carl P. Englert Jr.

I, _____, in a field survey on July 8, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-12
L.C.R.C Liber 4, Page 139, (12-10-80)
Found iron pipe from old ties, set C.I.M.
P.P. SE. 85.96'
T.P. NW. 45.71
35" Maple NE. 30.14'
St. Sign W. 23.98'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I -12
Found 4" Harrison Monument 6" deep
and accepted as a careful and faithful
perpetuation of the position of the
original corner.

P.P. SE. 85.96'
35" Maple NE. 30'± (no nail)
T.P. NW 45.71' (46.26m)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12 4" Harrison C.I.M.
O.C. Remon Tag & Nail in SE. side 32" Maple N 25 degrees E 52.43'
O.C. Remon Tag & Nail in S. side 26" Maple N 71 degrees E 88.14'
O.C. Remon Tag & Nail in cut off T.P. NE. side N 40 degrees W 46.26'
O.C. Remon Tag & Nail in SW side P.P. S 43 degrees E 86.16'
Centerline of Gravel Road 2'+
(Tape)

Signed by

Carl P. Englert Jr.

Date

December 3, 1993

Surveyor's Michigan License No.

18987

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 19, 1975
REVISED JAN., 1983