

SURVEY & REMONUMENTATION

DEC 01 1998

SECTION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

OTTAWA

(County)

Located In:

Corner Code #

1. Public Land Survey

T7N R 15W M-12 E 1/4 corner

T R Section 36)

T R Robinson Twp

T R A-12

2. Property Controlling in Section

S T R Common Corner

3. Miscellaneous Property in Sec.

S T R to A-12 T-14

4. Lot No. , Recorded Plat

5. Private Claims

I, Randal J. Vugteveen, in a field survey on April 16, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	10	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-12 Set by G.L.O. May 1832, C. Britain
10" Beech N19°W 30 links
10" Beech S64°W 19 links

Liber 4, Page 81 (June 1980)
M-12 Set Cast Iron Monument
Inscribed "Section Corner"
Power Pole ENE 73.45'
Telephone Ped. West 30.78'
SE corner house NW 85.92'
NE corner house SW 87.87'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-12 Found cast iron monument in monument box

Nail & tag N. side Power Pole AZ 77° 73.84'
PK in S. side Telephone Ped. Post AZ 270° 31.15'
SE corner house AZ 294° 85.88'
NE corner house AZ 238° 88.05'

Accepted cast iron monument as a careful and faithful perpetuation of the position of the original corner. This corner is common to A-12, T7N, R14W.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-12 Found Cast Iron monument in monument box

Nail & Ottawa Co. Remon. tag in N. side Power Pole AZ 92° 78.29'
Nail & Ottawa County Remon. tag in NE side Power Pole AZ 137° 92.65'
SE corner house foundation AZ 227° 115.98'
SE corner brick house corner AZ 294° 85.88'
Center of fire hydrant AZ 20° 128.91'
Centerline of Pavement West 2.5'

Signed by

Surveyor's Michigan License No.

28429

Date

July 25, 1998

LIBER 004 PAGE 175

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19
REVISED MAY 14, 19
REVISED JAN., 19
REVISED OCT., 19

\$9.00 CORNER
Receipt #13502