SURVEY & REMONUMENTATION

APR 2 5 1995

OTTAWA COUNTY REMONUMENTATION

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

91, DEC -8 PH 12: 39

For corners in		i mig noquit	r. 1910	2,14	-K. 254	10	Le	ine	40			
	Ottawa (County)	Located In:	Corner Code ##		15/5	REGIS OT TAW	TER O	F DE	EDS			
1.	Public Land Survey	T <u>8N</u> R <u>13W</u> T R T R	D-9 (S%,20) Wright Twp.									
2.	Property Controlling in Section	S T R S T R										
3.	Miscellaneous Property in Sec.	S T R S T R		Registe	r of D	eeds :	Stam	p & 1	File t	Nun	ıber	_
	• • • • • • • • • • • • • • • • • • • •	Recorded Plat			А В	C D	E F	G	H i	į J	к	L
Э.	Private Claims			2	_ 6	5 						 -
		in a field survey onOcto			_ 7	8 	9		10			12-
in :	lines 1 and 2 above were	equirements of P.A. 74, Michigan P.A. of in conformance with regulations and structions of the United States Departs	rules therefore as required in	the 6	18	— 1 <i>7</i> —	16	-	15—	—1 <i>4</i>	,	13-

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

D-9 % corner common to Sections 20 & 29, Wright Twp.

L.C.R.C. recorded in Liber 2, Page 79, 3-23-73 Fnd. 1/2" Iron Pipe Original Government Corner Record: Set or sec post between Sec. 20 & 29 Telephone Pole 31.85' Power Pole 49.65 Post N 16" Cottonwood Sugar 5 S79E SW 38.40' 8" Catalpa Do 15 N58W 25 NE 34.521

Enoch Hammele, Deputy Surveyor Between 9-18 and 9-26, 1838

expressed below:

(SEE REVERSE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-9 Found Cast Iron Monument inscribed "Section Corner" 9" below surface in Monument Box, and accepted as a careful and faithful perpetuation of the position of the original corner.

Found nail in face of Power Pole	North	49.62
Found nail in West side of Power Pole	North	50.04
Found PK nail in West side of Power Pole	North	50.10
Found PK nail in NW side of 12" Apple	N46°E	56.41'
Found nail in NE side of 7" Elm	S28°30'E	42.10'
Found PK nail in West side of 18" Twin Poplar	S06°W	48.95'
West end 12" Corrugated Metal Culvert	N44°W	36.2'



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-9 Set 3/4" X 6" solid bar with Ottawa County Remon Cap in Monument Dox, 2%" below surface over Cast Iron Monument inscribed "Section Corner".

Set Ottawa County Remon Tag & nail in Fast side of Power Pole

North

50.10'

016. 0000 1.01 1.01.0		
Set Ottawa County Remon Tag & nail in East side of Power Pole	North	50.10'
Set Ottawa County Remon Tag & nail in SE side of 12" Apple	N46°E	56.25'
Set Ottawa County Remon Tag & nail in NE side of 7" Elm	S28°30'E	42.10'
Set Ottawa County Remon Tag & nail in West side of 18" Twin Poplar	\$06°₩	48.97'
Set Ottawa County Remon Tag & nail in NW side of 9" Poplar	S60°30'W	78.70¹

On occupation lines North & South

Centerline asphalt road East & West, 0.5' North

P.A. 345 OTTAWA COUNTY

PEER PROVED 10/17/94

OCT. 17.1994

Surveyor's Michigan License No.

23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

PART A. continued

L.C.R.C. recorded in Liber 3, Page 56, 3-29-76 D-9 Set cast iron Mon. 6" triple locust NE 35.01' 32.24' 39.04' 50.10' Tel pole 14" poplar S SW P. pole N L.C.R.C. recorded in Liber 6, Page 45, 9-11-90 Cast Iron Monument in Monument Box Power Pole North 50.10' 4" Elm 18" Twin Poplar SE SSW 42.20' 49.10' W. end Metal Culv. NW 36.35'

N 3 9 5