## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

## For corners in

Ontonagon	Located In:	Corner Code #										
(County)	-											
1. Public Land Survey	TR											
2. Property Controlling in Section	S 33 T 52N R 37W S T R S 33 T 52N R 37W	7 (GCDB 400160)										
3. Miscellaneous Property in Sec.	S T R S T R	(GCDB 320100)		ogiste	or of D	eeds S	taman	e Fil.	- Nive	- h		
	corded Plat		. A		311			x riie	3 Nun	nber	_	
5. Private Claims			1 —	ВС	P	E F	G	H-		<u></u> K		М
	7 09	9/10/15	2 -	6	— <b>\$</b> -	╂═┋	+	د	<del> </del>	<u>-</u>	ļ	_
	n a field survey on 15 09 74, Michigan P.A. of 1970, the corner regulations and rules therefore as requi		3 4 5	<del>,</del>	8		1	-10-	1	1	-12	
	Department of the Interior, Bureau of L			18	17	16		 -1 5	,		13	
a Court of Law and /or that the o	corner points mentioned in lines 3, 4 and	d 5 above were in conformance with	7	1_				<u> </u>	<u>آــــا</u>		لَـــا	
the rules of the Michigan Board	d of Land Surveyors or by a Decree	of a Court of Law; established.	a L		20-	<u> </u>		22				
re-established, monumented, recover	ered, found as expressed below:	,	9			T-i	$\top$	1			24	П
			10	ĬΠ			$\top$				$\neg$	_
NOTE: Not more than 2 corn	ers, all in the same town and range	e. may be recorded	-	ľ	29_ 	28		27	<del> </del> 2	$\Box$	25 	
on this certificate.			11				-	1			_	$\neg$
			12	ï	—32— 	-33	_	34—	<del>-3</del> 1	5	—36	
A. Description of original m	onument and accessories and/or		13			-				_		

(7-Sec. 33) North 1/16 corner between Sections 33 and 34. Not previously monumented.

(15-Sec. 33) West 1/16 corner on the South line of Section 33. Not a common 1/16 corner with Section 4, T51N-R37W. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7-Sec. 33) Established the position for the corner midway and on the Section line between Section corner 1344.66' north and Quarter corner 1344.66' south.

(15-Sec. 33) Established the position for the corner on the Township line between Standard Quarter corner 1317.07' east and Section corner 1317.07' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Sugar N25°W 27.25' mrkd "1/16S BT" 13" Sugar N75°E 16.35' do 14" Sugar S19°W 20.8' do 10" Sugar N55°W 12.05' do Set sg'd cedar post adjacent.	(15) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  11" Sugar N77°W 9.05' mrkd "1/16S BT"  4" Sugar N27°W 16.75' do  4" Ash N14°E 7.15' do  10" Sugar N62°E 23.15' do  Set sg'd cedar post adjacent
Set sq'd cedar post adjacent. E= 7847825.107 N= 233037.664	Sugar N62°E 23.15' do Set sq'd cedar post adjacent. E= 7846603.179 N= 231839.776

Bearings are magnetic.	Coordinates are	MCS83 in meters,	NAD83 (2011)	Epoch 2010.00	datum.
Coord. Ref.=	NGS PID RL0503:	N= 233736.672 m.	E= 7856830	965 m	

igned by Stephen Synghosh

Date

09/23/2015

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Forest Resources Division