

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 17 T 53N R 37W	15
	S 17 T 53N R 37W	SMC N. of 6
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 15 08/29/2012 SMC 08/29/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 17) West 1/16 corner between Sections 17 and 20. Not previously monumented.

(SMC N. of 6) Special Meander Corner on the East 1/16 line of Section 17, north of the NE1/16 corner (1/16 corner #6). Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 17) Established the position for the corner midway and on the Section line between Section corner 1265.86' west and Quarter corner 1265.86' east.

(SMC N. of 6) Established the position for the corner on the East 1/16 line, having a bearing which is the mean of the East Section line and the N-S 1/4 line, 18 ft. South of the apparent Ordinary High Water Mark of Lake Superior and 790.24 ft. north of the NE1/16 corner of Section 17.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Sugar N06E 32.45' mrkd "1/16S BT"  
12" Cedar S62E 19.65' do  
4" Ironwood S46W 5.75' do  
12" Sugar N89W 13.5' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(SMC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Ash N38E 6.2' mrkd "SMC BT"  
4" Maple S40E 7.8' do  
9" Ash S11E 14.05' do  
6" Balsam N84W 7.8' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division

