

JAN 22 2001

LIBER

3 PAGE 36

SECTION

2000 Remonumentation Program
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

00 NOV 27 AM 8:55

LIBER NO. 3 PAGE NO. 36
MICHELE VANNORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

<u>Sanilac</u> (County)	Located in:	Corner Code #
1. Public Land Survey	T11N R15E	H - 1
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

2000

I, John A Milletics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.


	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes - None
Old Survey Liber - None
Act 132 - Liber 2 Page 18 Kay Eng, Liber 3 Page 764 Kay Eng
L.C.R.C. Forms- None
Unrecorded surveys - Milletics Oct 1997

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 1
N 1/4 Corner Section 3 T11N-R15E
Found 1/2" Iron in Monu Box
West 2624.05 feet to the NW Cor Section 3
East 2627.64 feet to the NE Cor Section 3
Accepted as best evidence



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 1
N 1/4 Corner Section 3 T11N-R15E
1/2" Iron in Monu Box
East 20.55 feet to the S 1/4 Cor Section 34
S20°E 23.90 feet to a nail in a Power Pole
S25°E 35.10 feet to a nail in a 24" Maple
N65°E 41.70 feet to a nail in a Power Pole
N35°W 31.10 to the center of a Fire Hydrant
West 2624.05 feet to the NW Corner Section 3
East 2627.64 feet to the NE Corner Section 3

APPROVED PEER BOARD
MEETING NOV 25 2000

Signed by John A Milletics
Surveyor's Michigan License No. 25859

Date Nov 15, 2000