

JAN 2 2 2001

SECTION

3 Mg 55 LIBER

RECEIVED FOR RECORD

00 NOV 29 AM 11: 11

For corners	in

3. Miscellaneous Property in Sec. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

2000 REMONUMENTATION PROGRAM _Sanilac Located in: Corner Code # (County) 1. Public Land Survey TIIN R16E 2. Property Controlling T in Section

LIBER NO. 3 R NO. PAGE 110. 55 MICHELE VANNORMAN REGISTER OF DEEDS SANILAC CO. MICHIGAN

Register of Deeds Stamp & File Number

_, Recorded Plat . Private Claims

2000 John A Milletics , in a field survey on May 1 do hereby state that under equirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in onformance with regulations and rules therefore as required in the current manual of survey instructions of the nited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan oard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

OTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

None

Act 132 - Liber 1 Page 162 I.E. Chope Oct 1971

L.C.R.C. Forms - None

State Highway Book - Page 73

Old Survey Liber - None

Unrecorded surveys - Milletics Oct 1990

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D - 1

N 1/4 Corner Section 5 T11N-R16E

Found no evidence of corner as site - State Highway Department removed

corner during construction.

West 2611.30 feet to the NW Corner Section 5

East 2693.00 feet to the NE Corner Section 5

Accepted as best evidence

APPROVED PEER BOARD MEETING Nov 25, 2000

MINIME COLUMN TO THE PARTY OF T

tonal

Atliffe

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

D - 1

N 1/4 Corner Section 5 T11N-R16E

1/2" Iron bar with cap in concrete

East 2.82 feet to the S 1/4 Corner Section 32

N30°W 49.20 feet to a nail in a 24" Maple

NO5°E 66.44 feet to a nail in a 24" Maple

N30°E 73.20 feet to a nail in a 20" Maple

West 2611.30 feet to the NW Corner Section 5

East 2693.00 feet to the NE Corner Section 5

ned by_ veyor's Michigan License No._ 25859

Date__ Nov 15, 2000

