

JAN 22 2001

LIBER

3 PAGE 51

RECEIVED FOR RECORD

00 NOV 29 AM 11:11

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
2000 REMONUMENTATION PROGRAM

LIBER NO. 3 PAGE NO. 51
MICHELE VANNORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T 11N R 16E

H - 1

T R

T R

T R

T R

2. Property Controlling
in Section

S T

S T

3. Miscellaneous

S T

S T

Property in Sec.

S T

S T

Register of Deeds Stamp & File Number

1. Lot No. , Recorded Plat

2. Private Claims

2000

John A. Millettich in a field survey on May 1, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Description of original monument and accessories and/or subsequent restoration:

H - 1

GLO Notes

None

L.C.R.C. Forms - none

Act 132 - None

Unrecorded surveys - None

State Highway Right of Way Book Page 74

Old Survey Liber - None

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 1

N 1/4 Corner Section 3 T11N-R16E

Found no evidence of corner on site - State Highway Department removed

corners during construction

West 2657.84 feet to the NW Corner Section 3

East 2669.90 feet to the NE Corner Section 3

Accepted as best evidence

APPROVED PEER BOARD
MEETING Nov 25, 2000

[Signature]

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 1

N 1/4 Corner Section 3 T11N-R16E

1/2" Iron Bar with cap in concrete

West 38.60 feet to the S 1/4 Corner Section 34

S05°E 54.85 feet to a nail in a Telephone Pole


S30°E 65.50 feet to a nail in a 8" Poplar

N40°W 74.30 feet to a Michigan Bell Riser Box

S50°E 51.60 feet to the west end of a 24" CMP

West 2657.84 feet to the NW Corner Section 3

East 2669.90 feet to the NE Corner Section 3



Recorded by *[Signature]*

Date Nov 15, 2000

Surveyor's Michigan License No. 25859