

SCHOOLCRAFT COUNTY  
PEER GROUP APPROVED

DATE 10/21/98 JOB

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &  
REMONUMENTATION

JAN 21 1999

SECTION

For corners in

Schoolcraft  
(County)

Located In:

Corner Code #

1. Public Land Survey

T41N R16W

A-2 ✓

T41N R17W

M-2

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

SIGRID HEDBERG

SCHOOLCRAFT CO. REGISTER

1P

Page 1 of 1

JLO Rec. Date 12/03/98

REVENUE FEES:

LC 14/ 207

Time 14:25

9:00

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Thomas P. O'Brien in a field survey on Oct. 22, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

A2 W 1/2 Corner Section 6, T41N - R16W

July 29, 1845 - John Burt D.S. set qr. section post common to section 6, T41N - R16W and section 1, T41N - R17W.

June 23, 1970 - L.C.R.C. by Frank J. Bray (L.3 Pg.399 RLS ) indicates "This corner was re-witnessed as set by unknown party. Corner has been accepted by adjoining landowners".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A2 Oct. 22, 1998 - Thomas P. O'Brien P.S. recovered iron rod buried below black top surface .30'. Replaced iron rod with I.B. and O'Brien cap # 21274 in Monument Box. Existing BT verifies corner location as found by Frank J. Bray on June 23, 1970.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A2 I.B. with O'Brien cap # 21274 set in Monument Box. Established the following references which are blazed, scribed, painted and tagged:

(Fd.) 18" Beech - S65°E - 52.90'

NBT 8" Maple - S57°W - 91.98'

NBT 8" Maple - N32°W - 110.81'

SW corner of brick house - N58°E - 79.62'

Centerline of Gravel Rd. East - North - 6.0'

Centerline of County Rd. 455 - West - 15.30'

Thomas P. O'Brien

Signed by Thomas P. O'Brien

Date November 29, 1998

Surveyor's Michigan License No. 21274

