## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 42-43 NR \_ 14W \_

Schoolcraft COUNT
DESCRIPTION OF CORNER Sec. Cor. 4-5-32-33
DESCRIPTION OF CORNER MONUMENT1" Pipe with 4" Brass Cap
WITNESSES TO CORNER 8" Cedar (S33 NBT) N50°E 56 Lks.
9" Cedar (S4 NBT) S56°E 11 Lks.
9" Cedar (S NBT) S54 W 29 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cor. from two Cedar stumps; probable B.Ts. bearing N25°E 30 Lks. and S38°W 13 Lks. Stumps both badly rotted; no identifying marks. Found old blazes on stumps and Cedar trees in vicinity. Distrance checks well to east. Distance north 2.50 chs. to small stream ok. Cor. placed and wit. 8/18/58 with C. Makel, D.F. and J. Zollner, Ass't.

CHEVEYORS SEAL

Billy D. Buckler

GNED \_\_\_\_\_\_\_

Billy D' Buckler

DATE \_ 7/30/59\_