MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_47. NR_18.#

			Seheeloraft COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between-Sections- 22-4-27
DESCRIPTION	OF	CORNER	MONUMENT1# Pipe with 4# Brass cap
WIT TNESSES	то	CORNER	28."-WPine-Stump N 52 -W68-Links
			RB_ N. Pine_Esump = S-1_E = 49 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Ferestry Division survey crew, while making a partial resurvey of this Tewnship. Two probable original B.T.'s still in place, badly burned.

Gerner was placed and witnessed May 27, 1955.

SURVEYORS SEAL

SIGNED LAND SURVEYOR STUDENTE DATE 188