MAY 28.1997

### REMONUMENTATION

### RECORDED

# COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

96 AUG 16 PM 2: 38

REGISTER OF DEEDS Krye Shudda

For corners in Located In: Corner Code # Shiawassee 1. Public Land Survey 7N R D-07 (NW 20) 1E R R R 2. Property Controlling R in Section 3. Miscellaneous R Property in Sec. S R

Register of Deeds Stamp & File Number

D

5

8

17

20

32

MICH

ER 4

16

21

28

33

10

15

22

27

34

11

14

23

26

35

12

13

24

25

36

1 2

3

7

9 10

11

12 31

18

19.96 Norman C. Caldwell in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

D-07 Closing Section Corner of Sections 17 & 20, T7N-R1E

\_, Recorded Plat

4 Lot No.

5. Private Claims

expressed below:

Post placed by Robinson Thomas, 24 January 1831
References: S 53 E 102 lks (67.32') 6" Ash
N 26 E 34 lks (22.44') 6" Elm
East 25 links (16.5') to center of creek (Maple River)

A 1903 survey for the Maple River Drain in Book #17 at page 7, Shiawassee County records, this position to be 30 links (19.80') South and 58 links (38.28') West of the center of the River.

Oliver M. Elliot, P.S. #2097, surveyed along the Michigan Meridian in 1950 +/-. #19 at page 41 ties to the southerly right of way of the railroad only. There His record in Book There are no ties to the Government Corners along the Meridian.

M.D.Q.T. right of way maps do not locate this corner.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

#### D-07 Closing Section Cor., Sections 17 & 20, T7N-R1E

No evidence of the original monument could be found.

This position was established by extending the west 1/2 of the south line of Section 16 to an intersection with the Michigan Meridian. The dimensions recited in the Maple River Drain are in close agreement with this location.

There is no apparent conflicting evidence and this pestablishment of the position of the original corner. evidence and this position is accepted as a careful and faithful re-

Approved by the joint Clinton/Shiawassee County Remonumentation peer group 22 May 1996.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

#### D-97 Closing Section Cor., Sections 17 & 20, T7N-RIE

Placed standard Harrison monument at intersection of Michigan Meridian and extended line 1/2 mile of the section line between 16 & 21.

References:

85.74 Found 3/4" pipe

#12018 Tag in 16" Maple #12018 Tag in 18" Maple S 85 R 33.98

S 80 E 54.97 South 61.731 #12018 Tag in 12" Ash

North 121 +/-South edge of Maple River

center of a N-S drainage ditch

County Remonumentation

Peer Review Group

E OF MICH NORMAN C. CALDWELL PROFESSIONAL SURVEYOR No. 12018 OFESSIO

Signed by

Date 3/ MAY 1996

Surveyor's Michigan License No. 12018