

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 22 T 47N R 17W	4
	S 22 T 47N R 17W	5
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 4 05/08/2012 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 22) Northwest 1/16 corner, Section 22. Not established in the original survey.

(5-Sec. 22) North 1/16 corner, Section 22. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 22) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

(5-Sec. 22) Established the position for the corner midway and on a straight line between Quarter  
corner 1319.81' north and the intersection of 1/4 lines of Sec. 22 1319.81' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" Sugar S63W 9.45' mrkd "NW1/16 BT"  
9" Sugar N33W 11.65' do  
8" Sugar N48E 8.65' do  
7" Sugar S36E 10.6' do  
Bearings are magnetic.

(5) Set 1"IDx36" I.pipe with plastic cap, flush  
with the ground on the NW side of 2-track trail.  
Set measuring nail with MDNR tag in the side of:  
11" Sugar N09E 9.15' mrkd "N1/16 BT"  
14" Sugar S51E 20.25' do  
11" Sugar S14W 26.9' do  
8" Sugar S70W 11.15' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/26/2012

For the Michigan Department of Natural Resources, Forest Resources Division

