SECTION

ALLEGAN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

00 FEB -1 /4 8:39

ncznw / n ii niiiiii Yayoo B. Colation
REGISTER OF THE TOTAL
ALLEGAN COUNTY STORM For corners in Located In: Corner Code # Allegan zИ R16W_ CD-1 Ganges Twp. 1. Public Land Survey T3N Sequence No. 2 R Ð. CD-13. Saugatuck 31. R 16 W. Twp., Sequence No. 3 R 2. Property Controlling S in Section Register of Deeds Stamp & File Number Section 32 3. Miscellaneous Saugatuck Twp. Property in Sec. _, Recorded Plat C D 5. Private Claims 2 2 3 12 A In. 41... in a field survey on December 4, 1999, I. Steve Lampen do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 15 14-13 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 7 10 20 21 22. 23. 24 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 27 25 10 28 26 30 29 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 36 33 35 12 31 32

GLO - L. Lyon - 1831 West on South side Section 32 60.95 to margin of Lake Michigan and set post Aspen 8 N8E 146'

62

Maple 6 S22W

Old notes Allegan County Surveyor Iron 728 feet West of the centerline of Lakeshore Road.

1980 J. Dillingham Iron 726.74 feet West of the centerline of Lakeshore Road.

1983 Steven Lampen found Iron 726.83 feet West of the centerline of Lakeshore Road.

Description of original monument and accessories and/or subsequent restoration:

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Iron found in 1983 gone due to erosion caused by Lake Michigan.

Set standard Allegan County Remon 1/2" x 24" iron with red cap #23520 - See sketch on back.

Approved by the Allegan County Remon Peer Group on December 14, 1999.

This position not established by original Government surveyors. This monument is accepted as the best available evidence of the position

Traversed 507' on Road and 692' off Road.

APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990

ALLEGAN COUNTY

DEC DATE APPROVED

COUNTY REP.

13

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

CD-1, Ganges Twp., Sequence No. 2 CD-13, Saugatuck Twp., Sequence No. 2

Standard Allegan County Remonumentation \" x 36" iron with red cap #23520.

271°

Azimuth = Michigan State Plane grid direction.

38° 46' 197.90' NW Corner House 122° 39' SW Corner House, 3' above ground 129.06' 43 ' NE Corner House, Brick 1110 75.08 163° 40' 53.88′ NW Corner House, Brick 9, Top Bank 271° 004

Signed by Steven

Surveyor's Michigan License No. 37279

Lake Michigan

Date DECEMBER 31, 1999

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

130

MAR 6 7 2000

SECTION

