

# Arenac County Remonumentation

LIBE? 02 PAGE 61

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Arenac (County)

Located In:

Corner Code #

- |                                    |   |     |   |    |     |
|------------------------------------|---|-----|---|----|-----|
| 1. Public Land Survey              | T | 18N | R | 4E | D 9 |
|                                    | T |     | R |    |     |
|                                    | T |     | R |    |     |
|                                    | T |     | R |    |     |
| 2. Property Controlling in Section | S |     | T | R  |     |
|                                    | S |     | T | R  |     |
| 3. Miscellaneous                   | S |     | T | R  |     |
| Property in Section                | S |     | T | R  |     |

RECORDED  
JAN 22 2 46 PM '96  
ARENAC COUNTY  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K
2	6		5		4		3		2	
3										
4	7		8		9		10		11	
5										
6	18		17		16		15		14	
7										
8	18		20		21		22		23	
9										
10	30		29		28		27		26	
11										
12	31		32		33		34		35	
13										

I, Craig W. McVean, in a field survey on June 23, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

### A. Description of original monument and accessories and/or subsequent restoration:

D 9 - Set 1/4 Section Post - J. Burt - 1843.  
Hemlk 10" N 60° E 11 Lks.  
Do: 10" S 46° W 8 Lks.

Recorded Survey - L. 1, P. 354 - found 1/2" iron in monument box in W'y S-bound lane I-75 - 1978

MDOT Witness Card - L. 1, P. 209 - Set "I" Iron Pin in fence corner. Considered by local residents as location of 1/4 corner - Dist. and angles relationship to C 9 and E 9 - G. Statterly - 1963

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D 9 - Find 1/2" iron rod (5/8" flared top) in monument box - 4.98' E of edge of concrete lane for S-bound I-75 per L. 1, P. 354. Measurements to C 9 and E 9 agree with recorded MDOT dimensions. Monument accepted as the best available evidence of the position of the original corner.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D 9 - Place 3" Arenac County brass cap on existing 1/2" iron rod in monument box.  
S 70° W 32.33' to capped 3/8" rebar.  
N 28° W 40.54' to capped 3/8" rebar.  
S 44° E 34.47' to capped 3/8" rebar.  
N 80° E 69.95' to capped 3/8" rebar.  
W 4.98' to Wedge concrete lane S-bound I-75.

ACCEPTED BY THIS ARENAC COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON  
22 Nov. 1995  
Paul M. Crowe  
PAUL M. CROWE, CHAIRMAN



Signed by Craig W. McVean  
Surveyor's Michigan License No. 39088

Date 12/19/95