## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

	i ming recquirement or	nocit, mion, r.A. 1910 as All	ienaea	
For corners in				
K			1	
Baraga	_ Located in:	Corner Code #		
(County)				
1 Public Land Curron	T D			
1. Public Land Survey	T R			
	TR			
2. Property Controlling				
in Section	S 9 T 48N R 32W S T R			
	S 9 T 48N R 32W	(GCDB 320540)	1	
3. Miscellaneous	S T R	(GCDB 320520)		
Property in Sec.	s T R	(0000 020020)	N	
			Register of Deeds Stamp	s & File Number
4. Lot No. , Re	corded Plat		register of Deeds Staffit	o & File Number
5. Private Claims			ABCDEFG	HIJKLM
	11	06/09/14	2 - 5 - 5 1	3  2
ı, Stephan J. Szyszkoski , i		06/04/44	3	
	•			_101112
above were in conformance with	74, Michigan P.A. of 1970, the corr	ner points mentioned in lines 1 and equired in the current manual of survi	2 5	
instructions of the United States	Department of the Interior, Bureau	of Land Management or by a decree	ey	
a Court of Law and /or that the	corner points mentioned in lines 3, 4	and 5 above were in conformance wi	10 7 1	-13-1-1413
the rules of the Michigan Boar	d of Land Surveyors or by a Dec	ree of a Court of Law; establishe	d. 9 19 30 31	
re-established, monumented, recov		·	9	-26-1-23-1-24-
NOTE: Not more than 2 core	ners, all in the same town and ra	inge, may be recorded	10 -30 - 29 - 28	27-26-25-
on this certificate.		,	11	<del></del>
			12 31 32 33	<del>-343536-</del>
A Description of original m	nonument and accessories and	(a.a)	13	
7. Ocsemption of originatin	ionament and accessories and	or subsequent restoration:		
ස්. 1		9. Not previously mon	STEP SZYS: L/ SURV	HAN J. ZKOSKI AND VEYOR
(II-Sec. 9) Southwest	: 1/16 corner, Section	<ol><li>Not previously monur</li></ol>	mented. 33	986
			CAN	DSUR
			The same of the sa	MANUFACTURE OF THE PARTY OF THE
B. Description of corner ev	idence found and/or method a	pplied in restoring or reestabli	shing corner:	
			•	
(8-Sec. 9) Establishe corner 1316.31' west	ed the position for the and the intersection of	corner midway and on a f 1/4 lines of Section :	straight line betwee: 9 1316.31' east.	n Quarter
		31		
(11-Sec. 9) Establish	ned the position for the	e corner at the interse	ction of straight lin	oo gommaatina
opposite 1/16 corners	3.	7,77	octon of strangme in	es connecting
93		3.50		- 0
C. Description of monumer	nt for corner and accessories e	stablished to perpetuate locati	ng the position of the come	r: ii
		•	S p	
/0\				
(8) Set I"IDX28" 1.p:	ipe with 2" alum. MDNR ith MDNR tag in the sid	<u>-</u>	x28" I.pipe with 2" a	lum. MDNR cap.
3" B.Spruce N61°E 11	ith MDNR tag in the sid.		nail with MDNR tag i	
7" B.Spruce S71°E 8.:				"1/16S BT"
6" Tamarack S20°W 20	.15' do			do do
5" B.Spruce S73°W 29				do
Set sq'd cedar post		Set sq'd ceda	r post adjacent.	
E= 7898841.751 N= 1	199564.986	E= 7898834.82	4 N= 199163.256	
•				
Bearings	are magnetic. Coordinate	es are MCS83 in meters (	NAD83 (2011) D	
Coord.	Ref.=NGS PID RL1468:	N= 199449.721 m. E= 790	0600 011 m	
A			m.	

Signed by Supplied Date 06/18/2014
Surveyor's Michigan License No. 33986