

## SECTION

**BAY COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

BAY COUNTY Located In: Corner Code #  
(County)

1. Public Land Survey T 14N R 5E PC # 6  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S 15&22 T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

*Charles F. MacDonell*  
REGISTER OF DEEDS  
BAY COUNTY, MICHIGAN

2000 JAN - 7 P 2:01

RECORDED

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, DALE L. WINECKE, in a field survey on NOVEMBER 3, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same Town and Range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

PC #6  
MEANDER CORNER WEST OF H-7  
POST SET BY J. MULLETT, MAY 1839  
5" PLUM TREE S 10°W, 1.78 CHAIN

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PC #6  
MEANDER CORNER WEST OF H-7  
SEARCHED THE APPARENT LOCATION OF THE MEANDER CORNER AND FOUND NO MONUMENTATION.  
NO RECORD OF THIS CORNER FOUND.  
CORNER RESET AT GLO DISTANCE (27.00 CH) 1782.00' FROM H-7 ON A LINE FROM I-7 THROUGH H-7 EXTENDED WESTERLY.  
POINT FALLS INSIDE THE GENERAL MOTORS POWERTRAIN FACILITY.  
POSITION ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

PC #6  
MEANDER CORNER WEST OF H-7  
SET 5/8" x 24" REROD WITH BAY COUNTY REMONUMENTATION CAP.  
N 23°W 101.67' TO CENTERLINE OF MONITORING WELL.  
S 12°W 57.56' TO 6' CHAINLINK FENCE RUNS SOUTHEAST-NORTHWEST.  
S 20°E 400.92' TO CENTERLINE OF MANHOLE.  
S 35°E 523.60' TO CENTERLINE OF FIRE HYDRANT.  
S 03°E 203.32' TO CENTERLINE OF MONITORING WELL.



Signed by Dale Winecke  
Surveyor's Michigan License No. 41915

Date 12/30/99

FBW-T 1999, P. 12

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 198  
REVISED OCT., 199

APPROVED LAND CORNER  
P.A. 345 OF 1990 - Bay County  
Date 11/01/99  
MH  
Michael MacDonald P.S.  
County Representative



005

11