RATIFIED BY THE BERRIEN COUNTY BERRIEN COUNTY REMONIMENTATION
OFFICIAL CORNER UNDER MICHIGANLAND CORNER RECORDATION CERTIFICATE
PUNCE ACT 345-0F 1990 Filing Requirement of Act 74, Mich. P.A. 1970
Fox corners in Located in: Corner Code # BERRIEN COUNTY PIPESTONE TWP. (I-5) NE COR. SEC.15
1. Public Land Survey T_5S R_17W I-5 SER 4
T R R Register of Deeds Stamp & File Number
2. Property Controlling S T R 11/02/99 111#6969 in Section S T R 11/02/99 111#6969 3. Miscellaneous S T R 11/02/99 111#6969 Property in Sec. S T R 11/02/99 STATE REMON FEI
4. Lot No, Recorded Plat A B C D E F G H I J K L M 5. Private Claims
2 - 6 - 5 - 4 - 3 - 2 - 1 - 3 - 4 - 7 - 8 - 9 - 10 - 11 - 12 -
I, Alan Bartlett in a field survey on June 1999 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.
A. Description of original monument and accessories and/or subsequent restoration: DEC 2 3 1999
(PLEASE SEE BACK PAGE) SECTION
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Verified Corner using existing witnesses. This corner approved by the Berrien County Remonumentation Peer Group of Surveyors on June 22, 1999.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set Berrien County Remonumentation Cap and 3' Galvanized Pipe in Mon Box Witnesses
Cut "x" in gutter pan N70W 72.19' Cut "x" in gutter pan N33E 59.76' Cut "x" in gutter pan S20E 68.16' Cut "x" in gutter pan S23W 56.40'
Corner is accepted as a careful and faithful perpetuation of the position of the original corner. ALAN
Signed by Date 11/01/99 Surveyor's Michigan License No. 35988

LIBER 4 PAGE 180

A77 \$9.00 A77 \$2.00

I-5 NORTHEAST CORNER SECTION 15 PIPESTONE TOWNSHIP T5S,R17W

GLO April 24 1830

John Mullett DS

North between Sections 14 & 15 80.00 Set Post Cor to Secs 10,11,14,15

Witnesses

S86W Beech 9 N79E Swamp Oak

Nov 1893

CB Pratt County Surveyor

made mention of this corner in misc notes

"Found Remains of old Witnesses and from these Govt Stake. Replaced with Stake under stone"

Feb 15 1972

Recorded Survey Liber 917 page 673

Iron in Mon Box Witnesses

N45E 42.67 Stop sign Post N.E. Cor Conc Culvert S45E 68.6 N45W 62.25 Stop Sign Post

1/2 mile distance between 15 and J5 = 2650.64

no date

Berrien Co. Road Commission

conc mon in mon box Witnesses. NW 38.3 Pear Apple NE 49.2'

mon box 2' +/ - West of C/L M-140

1/2 mile distance between H5 and I5 = 2633.4

Jan 23 1973

Recorded Survey Liber 945 Page 108 Southwest Survey & Engin., A. Howard RLS No. 2382

Mon. Box

3.26' West of M-140 C/L

May 1982

Survey Certificate, Merritt Engineering, H.D. Pelrce. RLS No. 20710

No Witnesses

1/2 mile distance between 15 & J5 = 2650.46 3.24

East c/l M-140

June 1999

Alan Bartlett #35988 Landmark Technologies

Found 3/4" Iron Bar in Mon. Box, 3' West of c/I M140

Witnesses

N70W 72.19' Cut "x" in gutter pan 59.76' N33E Cut "x" in gutter pan Cut "x" in gutter pan S20E 68.161 S23W 56.40' Cut "x" in gutter pan

NEC. 2 3 1999