FEB 0 8 1999 '

BECTION

Surveyor's Michigan License No. 33985

BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970

·	Filing Requi	rement of Act 74, wich. P.A	Tiber Will 3 Page UZ4Z
For corners in		·	Branch County Recorded
BRANCH COUNTY BUTLER TWP	Located In:	Corner Code #	12-07-19 9 8 13:52:41
1. Public Land Survey	T <u>5 S R 5 W</u> T R T R		Linda Lee Morrison-Mathews REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R T R S T R T R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims			A B C D E F G H I J K L 2 6 5 4 3 2 -1-1-
I, <u>EDWARD W. REED</u> , in a field survey on <u>SEPT. 28</u> , 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded			6 —18 —17 —16 —15 —14 —13— 7 ———————————————————————————————————
on this certificate.			12 31 32 33 34 35 36
QUARTER CORNER COMMON TO SECTIONS 6 & 7 A. Description of original monument and accessories and/or subsequent restoration:			ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT MEETING HELD ON
1825: R. CLARK JR, D.S. 1878 M. KNOWLES,. CO. & STONES AROUN 1973: DAVID BOONE, SU	- CORNER SET . SURVEYOR - FOUND ST D JRVEYOR - SURVEY TIED	TAKE & WITNESS, SET STON	E.R.Reed Co. Rep
B. Description of corner e	vidence found and/or metho	od applied in restoring or reestal	olishing corner:
FOUND IRON STAKE AS	DESCRIBED BY CUTCHEF	R IN LCRC # 0245 ON LINE W	/ITH CORNERS EAST & WEST
			tuate locating the position of the corner: FLUSH WITH PAVED ROAD SURFACE
4" SQUARE CONC POST IN LINE WITH FENCE NO 36" OAK RR TIE BRACE POST	RTH & IN CENTERLINE C S 75 W 8	3.15' OF E/W ROAD 4.12 TO NAIL & CAP 3.0 TO SE CORNER OF RR T	SURVEYOR
AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.			NO. 33985 LAND SUR
Signed by EDWARD W	Mu W / Lee		Date NOV. 4, 1998