

MAY 28 1997

CHIPPEWA COUNTY REMONUMENTATION CORNER COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey

T44N R 2W

C-4

T R

T R

T R

T R

2. Property Controlling
In Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

\$7.00 LAND CORNER

\$2.00 MSSR

2/28/1997 3:56:34 PM

Receipt #226

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 9 PAGE 383

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on 06/10, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-4 1/4 Corner Common to Sections 7 & 8, Town 44 North, Range 2 West

1845 - Original ties to set post: Fir 4, S85°W 09 links - Fir 8, N01°E 17 links.

1907 - County Surveyor Frederick H. Brown notes for Sections 7 and 8 indicate this corner midway between section corners 2641 feet north and south.

Circa 1970's - Harry W. Goodwin, RLS 5434, Certificate of Survey. Sketch shows corner with a distance of 40 chains to existing section corner south and 40 chains (2641' measured) to existing section corner north.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of corner. Re-established corner on line between section corners 2643.56 feet north and 2642.25 feet south on the extension of an old fence line to the east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" iron with cap #33142 in the centerline of Mackinac Trail, on the extension of a fence line to the east.

Witnesses:

Utility Pole, S33°E 138.04'

9" Scotch Pine, N70°E 74.04'

11" Scotch Pine, N42°E 93.33'

8" Scotch Pine, N58°W 62.32'

Note: Unless noted otherwise, distances are to a nail/tag #33142 in the side of the witness object. Bearings are compass bearings corrected for declination. Trees are blazed and painted.

Signed by Keith R. Waters

Date 12-30-96

Surveyor's Michigan License No. 33142

BOOK 9 PAGE 383