FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION For corners in

Chippewa County Remonumentation Corner

Chippewa County	Located in:			Corner Code #
Public Land Survey		T47N T T T	R2E R R R	E-2
Property Controlling in Section	S S	T T	R R	
	S S	T T	R R	

. Recorded Plat

\$7.00 LAND CORNER

\$2.00 MSSR

9 FEB 2001 10:32:36 AM Receipt #1201 RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS


ROOK 11 PAGE 230

Register of Deeds Stamp & File Number



I, Larry R. Rogers, P.S., in a field survey on December 08, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration: (E-2) 1/4 Corner common to Sections 4 and 5, Township 47 North, Range 2 East.

The original corner post was placed in 1845 by John Mullett. No other reference to this corner was found in the County ound ... Surveyor Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E-2) 1/4 Corner common to Sections 4 and 5, Township 47 North, Range 2 East. This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

OVUMEN OVUMEN No evidence of the original comer position was recovered. Found a corner fence post with remains of old fences to the North and West. The distance North to the Northeast corner of Section 5 measured 2632.5 feet. The position of the corner fence post was accepted as the most reasonable perpetuation of the original position of this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (E-2) 1/4 Corner common to Sections 4 and 5, Township 47 North, Range 2 East. Corner is a 3/4" x 24" iron with plastic remonumentation cap set in the center of the decayed remains of an old corner

fence post with remains of fences to the North and West.

Witnesses: 14" Cedar N28°W 38.99 feet 12" Spruce S60°W 18.35 feet S33°E 8" Balsam Fir 26.39 feet 6" Balsam Fir S82°E 17.02 feet Steel Fence Post 1.0 feet South

LAND Bearings are magnetic compass bearings. All distances are to a nail and tag in the side of the witness object unless noted.

Signed by Larry R. Rogers, P.S.

Surveyor's Michigan License No. 29251

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SUBVEYORS, JAN. 28, 1971

FAGE PAGE REVISED JAN. 1983

REVISED JAN. 1983

OF MICHIG

LARRY R.

ROGERS

NO.

29251

ENSED

ind Surveyo