

FEB 13 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

01 FEB 13 AM 10:08

Charles W. Feindt
REGISTER OF DEEDS

For corners in

Charlevoix Located In: Corner Code #
(County)

1. Public Land Survey T 33N R 8W C-8
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property In Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Wayne E. Boss, in a field survey on November 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

C-8 October 1841 Charles W. Cathcart D.S.

Section 1/4 post

- 1) Beech 6" S20° W 8 links (5.28)
- 2) Beech 6" S12° E 22 links (14.52)

July 27, 1976 L.R. Feindt, P.S.

Found 1/2 rod

- 3) 5" Maple S33°E 13.82'
- 4) 11" W. Ash N66° E29.15'
- 5) P. Pole S22° W 88.46'

July 1976, L.R. Feindt

Found 1/2 rod

- 3) 5" Maple S33°E 13.82'
- 4) 11" W. Ash N66° E29.15'
- 5) P. Pole S22° W 88.46'

September 27, 1980 N.B. Deyoung, P.S.

Found 1/2 rod

- 4) 12" Ash N70° E29.15'
- 3) 10" Maple S45° E 13.75'
- 6) Fence post East 23.30'
- 5) Power pole S15° W 88.40'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-8 November 3, 2000

Found 1/2 rod 10" below surface about 7 1/2 ft East of CL NS gravel road

- 4) 12" Ash N70° E 29.15' found MCF (3920) cap
- 3) 10" Maple S45° E 13.75'
- 6) Fence post (leaning) east 23.30'
- 5) Power pole S15° W 88.40- MCF (3920)
- 7) 24" Maple S41°E 28.14 found tag 20705

C-9 to C-8 GLO 40 chains (2640') measures 2641.09' MLF 2641.68'

C-8 to C-9 GLO 40 chains (2640') measures 2642.69'

Charlevoix Co. Surveyor

APPROVED

Signature *Mary C. Feindt*

Date: Dec 7, 2000

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8 Placed Charlevoix County steel marker

- 4) 12" Ash N70° E 29.15' found MCF (3920) cap
- 3) 10" Maple S45° E 13.75'
- 6) Fence post (leaning) East 23.30'
- 5) Power pole S15° W 88.40- MCF (3920)
- 7) 24" Maple S41°E 28.14 found tag 20705

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by *[Signature]*
Surveyor's Michigan License No. 20703

Date 12/15/2000

