

**FEB 22 2001**

STATE OF MICHIGAN  
COUNTY OF CHARLEVOIX  
RECEIVED FOR RECORD

00 DEC 21 PM 2:07

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

PEAINE TOWNSHIP

REGISTER OF DEEDS

**CHARLEVOIX**  
(County)

Located in:

Corner Code #

**1. Public Land Survey**

T 39N R 10W I-12  
T R  
T R  
T R  
S T R  
S T R  
S T R  
S T R

**2. Property Controlling  
in Section**

**3. Miscellaneous  
Property in Sec.**

**4. Lot No.**, Recorded Plat

**5. Private Claims**

I, **JAMES E. EVANS**, in a field survey **AUGUST 30, 2000** do hereby state that requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**A. Description of original monument and accessories and/or subsequent restoration:  
I-12 QUARTER CORNER COMMON TO SECTION 34 & 35 T39N-R10W**

GLO: Set quarter sec post  
8" Beech S89°E 29 lks (19.14')  
3" Beech N40°W 13 lks (8.58')  
Sept 25, 1845 by John Burt D.S.

Wayne E. Boss PS #20703  
Survey dated 6-17-1976  
Found ½" iron rod  
4" Apple S40°E 33.20' (1)  
Util pole N15°E 163.00' (2)  
Fence post West 55.10' (3)

John Ferguson PS #24595  
Survey dated 6-04-1981  
Found ½" rod  
3" Apple S73°W 60.2' (4)  
2' Apple East 27.70'  
2" Apple S80°E 36.3'

Mary C. Feindt PS #3920  
Survey dated 7-31-1992  
Found ½' rod  
4" Apple S40°E 33.20' (1)  
Util pole N15°E 163.00' (2)  
T-iron East 33.00' (5)

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner  
I-12 QUARTER CORNER COMMON TO SECTION 34 & 35 T39N-R10W**

Found ½" rebar #20703 in center line of gravel road.

Distance to I-11 2620.10' (GLO = 2640.0' CAE = 2620.09' SAC = 2619.99')  
Distance to H-12 2636.44' (JEF = 2636.59' SAC = 2636.36')  
Distance to I-13 2645.46' (GLO = 2640.0 WEB = 2645.42' SAC = 2645.34')

**C. Description of monument for corner and accessories established to perpetuate location the position of the corner:  
I-12 QUARTER CORNER COMMON TO SECTION 34 & 35 T39N-R10W**

FOUND ½" REBAR #20703 IN THE CENTER LINE OF EAST SHORE ROAD.

Utility Pole N 12° E 162.85' Found nail in SE side. (2)  
Fence Post West ± 55' Found post on ground (3)  
4" Apple S 74° W 59.98' Found nail in SE side (4)  
T-iron stake S 88° E 32.93' Found cap #21566. (5)  
3" Apple S 34° E 53.90' Set nail & cap #22431 in SW side.

And is accepted as the best available evidence of the position of the original corner.

Signed by  
Surveyor's Michigan License No

22431

Date

12-21-00

Charlevoix Co. Surveyor  
**APPROVED**

Signature *Mary C. Feindt*  
Date: 12-21-00

