JAN 6 - 2000

SECTION

For corners in

expressed below:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

THEFT GAME

land Survey Demander of
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A-Of 1990 On 3-3, 199 9
Soul B. Balliet
Chairman

Approved By Lielta County

_	DELTA (County)	Located In: Corner Code ##	Mar 4 1999
1.	Public Land Survey	T 39 N R 18 W F - 1 SAME T 40 N R 18 W F - 13 CORNER T 39 N R 18 W F - 3 T R R	9:00 AM 136 21/200 C Zhu
2.	Property Controlling in Section	S T R	Fig. of County, MF Rep. of County.
3.	Miscellaneous Property in Sec.	S T R S T R	Register of Deeds Stamp & File Number
		, Recorded Plat	A B C D E F G H I J K I
5.	Privatę Claims		2 6 5 4 3 7 2
		F-1 [N1/4 COR SEC 4] F-3 [N1/4 COR SEC 9]	3 4 7 8 9 10 11
I, _ do			

on this certificate.

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

F-1 [N1/4 COR SEC. 4] JOHN BURT, DS-1845-SET WOOD POST (CEDAR 09" N20"E 10 LINKS) (CEDAR 05" N59"W 14 LINKS) NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT MONUMENTATION

F-3 [N1/4 COR SEC 9] A.MERRYWEATHER, DS-1848-SET WOOD POST-(BIRCH 06" N42"W 15 LINKS)(BIRCH 06" S21"E 22 LINKS)
NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT MONUMENTATION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1 [N1/4 COR SEC. 4] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION AT BASE OF LARGE CORNER FENCE POST (DOWN) AT JCT OF ANCIENT FENCE LINES (N & W) WHICH ARE DOWN AND IN POOR REPAIR. AS THE CORNER POST FOUND IS SIMILAR IN SIZE & NATURE TO OTHERS FOUND THROUGHOUT THIS FARMLAND AREA WHERE CORNER MONUMENTATION WAS FOUND TO EXIST! HAVE ACCEPTED THIS POSITION TO BE THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.

F-3 [N1/4 COR SEC 9] FOUND IN PLACE AND BADLY BENT A 11/4" X 42" IRON BAR. ID CORNER MONUMENT FROM B-W COUNTY RD INPROVEMENTS AND ANCIENT FARM FENCES NORTH AND SOUTH. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS 70 THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER. DUE TO POOR CONDITION OF THE EXISTING MONUMENT, THE LOWER 18" WAS CUT OFF AND DRIVEN TO REFUSAL.



REVISED JAN., 1983

10

11

12

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1 SET A BERNTSEN AINB30 ALUM MONUMENT W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

ASH 05" ASPEN 06" CEDAR 08" CEDAR 04" SURVEY MONUMENT SIGN POST N24°E S52°E S24°W N62°W SOUTH 53.45' 04.24' 52.48' 67.72' 1.20' (TO FACE)

F-3 SET, OVER EXISTING MONUMENT, A 5/8" X 18" REBAR W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

5/8" X 18" REBAR W/A 2" ALUN WIT CAP ASH 05" SURVEY MONUMENT SIGN POST N45"E N45"W SOUTH 27.52' 28.10' 75.45' 25.10' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Signed by	MPA	4Vis	Date	3/1/99
Surveyor's Michi	gan License No	16926		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971