## SECTION

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of

ALPHA 4

LAND CORNER RECORDATION CER

۲	.A. OI 1990	Ondicentu 3	<u>2, 199 </u>
TIFICATE_	Hend	Dlimeli	ij
D A 1070	acting	Chairman =	J

F	or corners in	Filing Require	ement of Act 74, Mich. P.A. 197	70 Acting Chair	nan
_	DELTA (County)	Located In:	Corner Code ##	^ /	.006
1.	Public Land Survey	T <u>40 N R 15 N</u> T <u>40 N R 19 W</u> T R T R	MC E-1/2 (25) A MC E-8/9 (13) 3	1000000 Jan 4 3:40 30000 1	1999 DM 12-
2.	Property Controlling in Section	S T R S T R		Deta County, Milifely of Chests	
3.	Miscellaneous Property in Sec.	S T R S T R	R	egister of Deeds Stan	np & File Number
I, do	M.P. DAVIS  hereby certify that under lines 1 and 2 above were irrent manual of survey insanagement or by a decree love were in conformance burt of Law; established pressed below:	E-1/2 [MC SEC 5/4] E-8/9 [MC Sec	of 1970, the corner points mentioned drules therefore as required in the ment of the Interior, Bureau of Landr points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a nonumented, recovered, found as	A B C D E  2 6 5 4  3 4 7 8 5  6 18 17 11  7 8 19 20 2  9 10 30 29 20  11 12 31 32 3	F G H I J K L M  3 - 2 - 10 - 11 - 12 - 13 - 14 - 14
A.	E-1/2 [MC SEC. 5/4] A NO RECORD EVIDENCE E-8/9 [MC SEC 20/21] A	al monument and accessories andMERRYWEATHER, D.S 1848 - WOOD OF SUBSEQUENT CORNER RECOVERY ANMERRYWEATHER, D.S 1848 - WOOD OF SUBSEQUENT CORNER RECOVERY AN	POST - (TAMARACK 06° S70°W 62 LINK D/OR RESTORATION POST (WILLOW 04°-N25°E-32 LINKS)	13	
В.		1	pplied in restoring or reestablishin	a corner	

- - E-1/2 [MC SEC. 5/4] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION AT "GLO" BEARING AND DISTANCE SE OF THE MC, AS ESTABLISHED BY B.L.M. SURVEY CREW IN 1997, ON THE 4TH CORRECTION LINE NORTH AT ITS' INTERSECTION WITH THE WESTERLY SHORE OF MOSS LAKE. THIS POSITION FITS WELL WITH THE PRESENT SHORE LINE OF MOSS LAKE.
  - E-8/9 [MC SEC 29/21] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION BY IDENTIFYING M.S. McNABB'S SECTION LINE X-ING AS FOUND IN HIS 1933 ROAD ALIGNMENT SURVEY OF COUNTY ROAD 499 EXTENDING A LINE SOUTH FROM THE WEST 1/4 COR OF SEC 21 THRU MCNABB'S K-ING POINT AND ESTAB-LISHING THE M.C. ON THIS LINE AND AT THE "GLO" DISTANCE (2451.9') SOUTH OF THE 1/4 CORNER. THIS AREA HAS BEEN ARTIFICALLY FILLED AND THE MOUTH OF THE STURGEON RIVER HAS APPARENTLY BY REROUTED DURING THE DEVELOPEMENT OF THE SMALL VILLAGE OF NAHMA AS THE CORNER POSITION FALLS A CONSIDERABLE DISTANCE FROM THE RIVER & LAKE MICHIGAN.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - E-1/2 SET BERNTSEN AINB30 ALUM MONUMENT W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

TAMARACK 09" TAMARACK 10° TAMARACK 11" TAMARACK 15\* SURVEY MONUMENT SIGN POST

S80°E S18°E S85°W N40°W NORTH 17.201 17.57 1.84' (TO FACE)

E-8/9 SET BERNTSEN AINB30 ALUMN MON. W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

OAK 10" OAK 09" SURVEY MONUMENT SIGN POST

NOTE: OPEN & TAG ALDER LAND IN THE NE & NW QUADRANTS

S35°E S40°W

14.25 54.91

SOUTH 1.31' (TO FACE)

BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Date Surveyor's Michigan License No. 16926