

SURVEY &
REMONUMENTATION

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

DELTA

(County)

Located In:

Corner Code ##

1. Public Land Survey T 40 N R 22 W B-5 & E-7
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
[B-5] N1/4 COR SEC 18 [E-7] NW COR SEC 21

I, M.P. DAVIS, in a field survey on NOVEMBER, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-5 [N1/4 COR SEC 18] WOOD POST - A. MERRYWEATHER, D.S. - 1846 (TAMERAC 7°-N29°E-25 LINKS) (TAMERAC 10°-S37°W-37 LINKS)
C.E. BROTHERTON - 1885 - STAKE IN PLACE - NO NEW WIT'S NOTED
M.S. McNABB - 1932 - NO EVIDENCE OF COR MON FOUND - ESTABLISHED BETWEEN COR'S - SET IP - CEDAR STUMP 14°-S30°E-20.5'

E-7 [NW COR SEC 21] WOOD POST - A. MERRYWEATHER, D.S. - 1846 (W.PINE 22°-N30°W-94 LINKS) (NORWAY PINE 18°-S60°E-96 LINKS)
GEORGE NAULT-RLS 6521 (FOR M.D.O.T.) 1971 - FOUND IRON PIN ON PLACE (J.PINE 12°-N70°E-32.19') (CONC MON EAST 30.0')
(OAK 16°-S65°E-18.36') (JACK PINE 5°-S40°E-20.81') (PP-WEST-19.30')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5 [N1/4 COR SEC 18] FOUND McNABB'S 1932 IP - ID FROM HIS CEDAR STUMP BT - IRON MARKS STILL PLAIN
ACCEPTED EXISTING AS A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL COR

E-7 [NW COR SEC 21] FOUND IRON PIN AS DESCRIBED IN M.D.O.T. RECORDS - ACCEPTED EXISTING MON AS A
CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 REPLACED EXISTING MONUMENT W/A BERNITSEN AINB30 ALUMN MON WITH CAP STAMPED TO ID THE COR POSITION
CEDAR 7" SURVEY MONUMENT SIGN POST CEDAR 5" CEDAR 7"
N46°W N45°E S13°E S68°W
19.70' 2.59' (TO FACE) 16.04' 20.77'

E-7 SET, OVER EXISTING MON, A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE COR POSITION & RAISED TO RD SURFACE W/A MON BOX
CONC MON NW COR CONC TELE PAD OAK 13"
WEST N72°E S40°E
33.0' 28.12' 53.92'

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS OTHERWISE NOTED

Signed by M.P. Davis Date 11/15/93
Surveyor's Michigan License No. 16926

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On Jan. 20, 1994

Sheila Schumling
Acting Chairman

Recorded January 21, 1994

9:00 o'clock a.m. in Liber 7 Page 355

Walter C. Thorne Reg. of Deeds,
Delta County, Michigan

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

