

SURVEY &
REMONUMENTATION

DEC 18 1995

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

REC'D NOV 21 AM 11:25

For corners in

Dickinson
(County)

Located In:

Corner Code #

1. Public Land Survey T 40N R 29W C-1
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

REGISTERED DEEDS
INDEXED
FILED

Register of Deeds Stamp & File Number

Section Corner common to Sections 6/5

I, Robert F. Perkins, in a field survey on Feb. 27, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1849 J.H. Mullett, D.S.
Set Post
Hemlock 10" S58°E .04 L.
Birch 16" S33°W .28 L.
1954 D. DeLaMater, RLS
Set D.N.R. Pipe Marker from Original B.T.
N.B.T. Y. Birch 24" N14°E 9 L.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1-31-95 Found above noted D.N.R. Marker and Y. Birch B.T.

ACCEPTED BY THE DICKINSON CO.
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC
345 OF 1990 AT A MEETING HELD

11/6/95

R.F.P.

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New Bearing Trees Marked.
Cedar 10" N39°E (M.B.) 57.49'
S.Maple 7" S61°E (M.B.) 57.50'
S.Maple 8" S26°E (M.B.) 8.0'
S.Maple 7" S78°W (M.B.) 6.2'

Signed by Robert F. Perkins

Date Feb. 27, 1995

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

