SUBVEY & REMONUMENTATION

MAR 1 3 2000

S	CUMFI	MICHIGAN COUNTY
	PFr:	ולהלה הממעו ו

	- Table	~	1	0	Â
O	二	Qл	ΝВ		1

Surveyor's Michigan License No. 33983

LAND CORNER RECORDATION CERTIFICATE

99 DEC 28 AM 9: 35 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code # **EMMET** CENTER TOWNSHIP 1. Public Land Survey T_37N _R5W ECRP #72A 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. Recorded Plat _ 5. Private Claims 12 I, <u>Richard E. Oelke</u>, in a field survey on <u>10 December</u>, 19 <u>99</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 -15 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, 10 ...3'n. -29-. ว่า ... --27--26-2.5 found as expressed below: į. 11 NOTE: Not more that 4 comers, all in the same town and range, may be recorded 34-on this certificate. . j A. Description of original monument and accessories and/or subsequent restoration: GLO set corner in 1840's. Trowbridge found ½" rod in 1983. This point has been used in subsequent surveys by local surveyors. APPROVED LAND CORNER P.A. 345 OF 1990 See back page for chronological history of corner. **Emmet County** .E. CELLE B. Description of corner eyldence found and/or method applied in restoring or reestablishing corner: ½" iron rod, 2' long, set by persons unknown. This point falls +/-6' N of centerline of Division Road and +/-6' E of the centerline of a dirt two track to the south. Fits old fence to the North, +/- 39' S of old N right-of-way fence. Falls in a road cut area. 3) N 31° E, 37.21', 5" aspen, tagged w/ a yellow cap in N face 6) N 51° E, 55.35', 3" aspen, tagged 33984 in SE face pp, tagged 15410 in NW face 2) S42° W. 51.95 4) N 05° W. 33.46', 8" aspen, tagged w/ a yellow cap in SW face C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set: The ½" rod noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program Cap. This position is accepted as a careful and faithful perpetuation of the position of the original corner. MICH **Additional New Witnesses:** RICHARD E N 52° E. 6" maple, tagged 33983 in W face 67.99', OFLKE 69.41', S 33° E. 10" apple, tagged 33983 in W face **PROFESSIONAL** N 53° W, 69.90', 4" aspen, tagged 33983 in E face SURVEYOR No. 33983

Date 10 December 1999

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION

LIEGR <u>A</u>
PAGE <u>301</u>

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 72A

37-5-A3

T37N R5W cor. bet. SECS. 1,6,7, and 12 west line of Twp. DIVISION ROAD and an unnamed road S.

Date	Surveyor	Found	Witnesses		Notes	
1840	GLO	Set post	1) NO1°E, 34I 2) S25°W, 40			
1968	Green	ECRC work in section 7				
1983	Trowbridge	Survey for Garber, found				
	ŭ	,	1) N11°E,	38.17'	6" poplar	
			2) S46°W	51.95	рр	
1990	Green	found ½" rod added new witness.				
			3) N 38°E,	37.40',	5" aspen	
		:	4) N O1 °W,	33.55',	5" aspen	
1997	Hall	found ½" rod				
			2) \$48°W	51.88	pp	
	•		3) N 44°E,	37.42',	4" aspen	
			5) N 58°E,		4" aspen	
			6) NO2°W,	38.47'	7" poplar	