

Register's Office } ss.  
Gogebic County }

Located In: Corner Code ~~##~~

Received for record the  
16<sup>TH</sup> day of ~~DECEMBER~~  
A. D. 19~~94~~ at 10:45 o'clock  
A m., and recorded in  
Liber 5 of CORNERS  
on page 168  
Ramona Collins, Deputy  
Register of Deeds

**Register of Deeds Stamp & File Number**

- |                                    |                           |        |
|------------------------------------|---------------------------|--------|
| 1. Public Land Survey              | T <u>47N</u> R <u>47W</u> | A-B-1  |
|                                    | T _____ R _____           | 001    |
|                                    | T _____ R _____           |        |
|                                    | T <u>48N</u> R <u>47W</u> | A-B-13 |
| 2. Property Controlling in Section | S _____ T _____ R _____   | 001    |
|                                    | S _____ T _____ R _____   |        |
| 3. Miscellaneous Property in Sec.  | S _____ T _____ R _____   |        |
|                                    | S _____ T _____ R _____   |        |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_  
Meander corner common to Section 6, T47N, R47W and  
Section 31, T48N, R47W.

I, John R. Garske, in a field survey on December 7, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by William Ives, Deputy Surveyor, in 1848. Original corner was a cedar post and original bearing trees are: Hemlock 18" - N25°E, 28 links (18.48'); Hemlock 26" - S9°W, 34 links (22.44').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence could be found. Corner position was re-established on the extension of the section line in conjunction with an ancient fence line west to the river's edge. The corner was placed at the top of bank so as to protect and preserve the integrity of the corner. This position matches G.L.O. call with measurement to the edge of the Montreal River.

**Record research form on file with County Register of Deeds office. See sketch on back.**

## PEER GROUP.

**Approved**

Richard P. Wrahn 12/15/84

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2 1/2" x 30" aluminum monument with a 3 1/4" aluminum cap stamped: County Remonumentation; T48N, R47W, M.C.; S-31; S-6; T47; 1994; RLS 28410. Established the following bearing trees and reference object: 8" twin hemlock east, 27.03 feet; 8" sugar - S35°E, 50.14 feet; 5" sugar - S15°W, 13.05 feet; 6' steel rail with sign - N10°E, 2.36 feet.

**Signed by**

Surveyor's Michigan License No. 28410

Date \_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

Fed. A-1-2

MONTREAL RIVER

2811.6' G.L.O.  
2807.65'(m)  
164.28(m) 31  
171.6' G.L.O.  
171.4'(m)

T48N, R47W

NORTH  
NO SCALE

2640' G.L.O.  
2636.29'(m)

T47N, R47W

31 32  
C 5