## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



T. <u>52</u> N.R. <u>36</u> W

_	Houghton		COUNTY
DESCRIPTION OF CORNER 1/4 Corner for Section 15, 16		<u> </u>	
CORNER MONUMENT			
DATE MONUMENT PLACED AND WITHESSED			
WITHESSES TO CORNER 10" Hemlock (1/4 S)(NBT)	S 47° E	13 links	
9 <sup>th</sup> S. Maple (1/4S)(NBT)	N 22° W	lik links	
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was found by Copper Range Co. but was re-witnessed previously by  $P_{\bullet}A_{\bullet}$  Larsen, Hancock.

No original evidence at this time.

SURVEYOR'S SEAL

REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE April 13, 1964