	Sunter 1
- ,	DRUMENTATION.

JAN 192001

SECTION

Man Leker 2, Page 114

2000 REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

For Corners in BINGHAM	Township	equirement of Act	74, Mich. P.A	. 1970		
Huron (County)	Located in:	Corner Code #			STATE OF MI HURON CO RECORD	UNTY
Public Land Survey	T 15N R 13	~~~~			8 DEC 2000	
Property Controlling S in Section S Miscellaneous S Property in Sec. S	T R T R T R T R T R	**************************************		Register	FRANCES L. I REGISTER OF of Deeds Stamp	DEEDS
4. Lot No, Recorder	d Plat			1A 8 C D	F F G U .	
5. Frivate Claims				2 - 6 3 - 3		
I, Russell L. Brown, in a fie requirements of P.A. 74, Michig above were in conformance wi manual of survey instructions of Management or by a decree of lines 3, 4, and 5 above were in Surveyors or by a Decree of recovered, found as expressed I	th regulations and rules the United States Depa a Court of Law and/or conformance with the a Court of Law; establedow:	the points mentioned is therefore as required itment of the Interior, it that the comer point rules of the Michigan ished, re-established,	in lines 1 and 2 t in the current Bureau of Land s mentioned in Board of Land monumented,	6 - 18 17 7	21 22	-11
NOTE: Not more than 2 corn on this certificate.	ers, all in the same to	wn and range, may l	be recorded	12 5 2	-3334	35 36
A. Description of original moi 1834 G.L.O. H. Parke D.S., Hemlock 18 N46W 14, COUNTY SURVEYORS RE COUNTY ROAD COMMISS Spike N.E. Base T.P. S30E L.C.R.C None RECORDED SURVEYS - COUNRECORDED SURVEYS	Beech 18 S58 1/2V CORD - None ION RECORD - No of 47.6, 8" Elm Tree No	ions 24 and 25, Eas V 18	t side T15N-R	12E.	N64E 78.1	
B. Description of corner evider No evidence of original corner	ce found and/or meth	od applied in restori d.	ng or reestabli	shing corner:	OF MIC	
Found 3/4" Dia. Re-Rod in M	onument Box.				RUSSELL L	N. C. Wall
Accepted found 3/4" Dia. Re-				III THE STATE OF T	LAND SURVEYOR NO. 24588	No do Maria
C. Description of monument for A-9 S. W. Cor. Sec. 19, and I Found 3/4" Dia. Re-Rod in Mo WITNESSES:	nument Box	es established to per 5N-R13E	petuate locatii	ng the position o	of the corner:	
N45°W 64.05' Spike in N.E. Fa N45°E 76.23' Spike in N. W. Fa S45°E 95.55' Spike in S. W. Fa S40°E 45.70' to 3/4" Re-Rod in South 2649.21' A-10, W. 1/4 (North 2628.21' A-8, W. 1/4 (ace of Power Pole ace of Power Pole Center of Project Ma Con Sec. 20, T45N Re		NOT This M-9	TE: Corner is comr , T15N-R12E	non with	
Signed by / Justill L. Surveyor's Michigan License No.	Brown)	Date _	Nov. 2	. 20 <i>0</i> 0		

JACOMENTATION

JAN 192001

SECTION

Re Mon Leker 2, Page 11.

2000 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing requirement of act 74, Mich. P.A. 1970

For Corners in BINGHAM Township

Huron County, T15N-R13E A – 9 Continued

RECORDED SURVEYS:

3-30-79, Case Surveying, Stewart G. Case P.S. 15399, Liber 4 Surveys, Page 15 of Huron County Records. S.E. Cor. Sec. 24, T15N-R12E

5/8" Iron Pin in Monument Box

WITNESSES:

West Corner Federal Project Marker, N45°E 59.65' West Corner Federal Project Marker, S40°E 45.05' Spike N.E. Side Power Pole, N30°W 64.35'

