

2000 REMONUMENTATION

Re-Monumentation 2, Page 93

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in

Huron
 (County)

Located in:

Corner Code #

 STATE OF MICHIGAN
 HURON COUNTY
 RECORDED

29 NOV 2000 11:21 AM

 FRANCES L. HOLDWICK
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land survey: Brookfield T 15 N R 10 E A-2
- T R
- T R
- T R
2. Property Controlling S T R
- in Section S T R
3. Miscellaneous S T R
- Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

I, James T. Meek, in a field survey on October 1, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 Original survey, West Bdy. T15NR10E, 1835, Harvey Parke D.S.

- A-2 West ¼ Corner of Section 6
- Post
- Elm 20", S17°W, 21 links
- B. Ash 10", N31°W, 29 links

County Surveyor's Record: iron pin
 Recorded Surveys: L2, P553 (Case)
 LCRC: none

 SURVEY &
 MONUMENTATION

JAN 19 2001

SECTION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-2 West ¼ Corner of Section 6

Found 1" iron in mon box
 2' South intersection of Bay Port & Oeschger Roads

Accepted as the best available evidence
 of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-2 West ¼ Corner of Section 6


1" iron in mon box

From which:

Road sign post bears N50°E, 37.7'
 Tag in power pole bears S45°W, 49.0'
 Road sign post bears S60°W, 40.6'
 ½" iron bears N45°W, 37.0'
 A-1, Corner of T15-16N, R9-10E bears N0°09'34"W, 2541.38'
 A-3, Corner of Sections 6,7 bears S0°09'19"E, 2643.58'

Signed by

Date

Surveyor's Michigan License No. 39089APPROVED AT PEER BOARD MEETING 11-02-00 RLB

BOARD OF LAND SURVEYORS, JAN 28, 11
 REVISED MAY 14, 11
 REVISED JAN, 11
 REVISED OCT, 11